Address
City
State
Date Survey
Date Negotiated

1504 SW 8th Avenue Topeka KS 6/10/2008

Item	Year		Area of						Estimated	
#	Built	Floor	Condition	Condition	TC	ADAAG	Recommendation	Photo	Cost	Comments
001	1988	1	South Lot-East Side	Walkway leading from the public sidewalk to the main		403.3	Reconstruct walkway to provide a maximum 2% cross slope for	001		
				entry has a cross slope ranging between 2.8%-3.3%.			entire route.	002		
				, , ,				003		
002	1988	1	South Lot-East Side	Walkway leading from the public sidewalk to the main		505.1	Provide handrails on any portion of walkway that has a slope which	002		
				entry has a portion 12' in length with a long slope of			exceeds 4.6% for a distance beyond 6'.			
				6.7%, but no handrails. This area is considered a			,			
				ramp, not a slope.						
003	1988	1	South Lot-East Side	There is no accessible route from access aisles to		502.3	Stripe 3 additional spaces adjacent to west side accessible spaces	002		
000	1000	<u> </u>	Codin Lot Last Glac	main entry without entering a vehicular lane of traffic.		302.3	and make east side spaces standard spaces. This will reduce the	004		
				main chity without chiefing a vehicular lane of trame.			amount of construction required to meet ADA standards.	004		
							East side would need new ramps, walkways and spaces graded.			
							East side would fleed flew famps, walkways and spaces graded.			
004	1988	1	South Lot-East Side	The designated accessible spaces have cross slopes		502.4	Stripe 3 additional spaces adjacent to west side accessible spaces	005		
004	1988	-	South Lot-East Side	ranging from 3.5%-4.1%.		302.4	and make east side spaces standard spaces. This will reduce the	005		
				ranging nom 5.5 %-4.1 %.			amount of construction required to meet ADA standards.	007		
								007		
							East side would need new ramps, walkways and spaces graded.			
005		4	Court Lat Foot Cida	The decimant decreasible areas being large classes of	000	E00.4	Chair - 2 - dditional diat tot -idibl	005		
005	1988	1	South Lot-East Side	The designated accessible space have long slopes of	002	502.4	Stripe 3 additional spaces adjacent to west side accessible spaces and make east side spaces standard spaces. This will reduce the	005 006		
-				2.5%.						
							amount of construction required to meet ADA standards.	007		
							East side would need new ramps, walkways and spaces graded.			
006	1988	1	South Lot-East Side	There is not a space marked van accessible, per		502.2	Stripe 3 additional spaces adjacent to west side accessible spaces	005		
				4.1.2 (5)(b)		502.6	and make east side spaces standard spaces. This will reduce the	006		
							amount of construction required to meet ADA standards.	800		
							East side would need new ramps, walkways and spaces graded.	009		
	1988						Raise sign to height of 60 inches as measured from parking lot grade			
007		1	South Lot-East Side	Sign are at 52" to the bottom.		502.6	to the bottom edge of the sign.	005		
								006		
								008		
								009		
000	4000	-1	South Lot- West Side	Existing ramp has a long slope of 11%.		405.2	Departigues comp to greate a long clone of 4:42 (9.20/) or better	010		
800	1988	-	Ramp from public	Existing ramp has a long slope of 11%.		405.2	Reconfigure ramp to create a long slope of 1:12 (8.3%) or better,	010		
-							per 4.8.2.	UII		
	-		walkway to spaces and		-					
			main entry							
000	4000	1	Courth Lat West C:	Evipting rooms had a run of 6.4/01 but no benefits		EOE 4	Drovide handraile on new rown ofter alone of 0.20/ or hattards	011		
009	1988	Т	South Lot- West Side	Existing ramp has a run of 6 1/2', but no handrails.		505.1	Provide handrails on new ramp after slope of 8.3% or better is	011		
<u> </u>			Ramp from public				achieved.			
			walkway to spaces and							
			main entry							
046			O . II I . I . W I C'.	MCH - I - P - C - d - I P - C I - P - C		400.0		040		
010	1988	1	South Lot- West Side	Walkway leading from the public sidewalk to the main		403.3	Reconstruct walkway to provide a maximum 2% cross slope for	012		
			Walkway in front of	entry has a cross slope of 3% in front of spaces.			entire route.			
			spaces leading to entry.							
011	1988	1	South Lot- West Side	Existing ramp has a cross slope of 4.6%.		405.3	Reconfigure ramp to create a cross slope of 2% or better, per 4.8.2.	013		
			Ramp leading from							
			spaces to main entry							

Item	Year		Area of						Estimated	
#	Built	Floor		Condition	TC	ADAAG	Recommendation	Photo	Cost	Comments
012			South Lot- West Side	Sign is at 53" to the bottom.	<u></u>		Raise sign to 60" to the bottom.	014	0001	Comments
012	1900	<u> </u>	Codin Edi Woot Cido	Olginio di obi to the bottom.		700.1.1	Traise digit to do to the bottom.	015		
								016		
								010		
013	1988	1	South Lot- West Side	There is not a space marked van accessible, per		502.2	Mark at least one space van accessible, per 4.1.2 (5)(b).	014		
	1300			4.1.2 (5)(b)		502.6	(-)(-)	015		
				(*)(*)				016		
014	1988	1	South Lot- West Side	The passenger loading zone has a cross slope of		503.4	Level passenger loading zone to a slope of 1:50 (2%), per 4.6.6.	017		
	1000			4.7%.			(=, p, g			
015	1988	1	South Lot- West Side	Walkway leading from parking to covered entry has a		403.3	Reconstruct walkway to provide a maximum 2% cross slope for	018		
				cross slope of 9.9%.			entire route.			
016	1988	1	South Lot- West Side	Existing ramp has a long slope of 9.9%.		405.2	Reconfigure ramp for a slope of 1:12 (8.3%) or better, per 4.8.2.	019		
017	1988	1	Back Lot	The designated accessible space does not have an			Provide an access aisle at each space, per 4.6.3.	020		
				access aisle.		502.3.1		021		
018	1988	1	Back Lot	There is not a space sized or marked van accessible,			Make at least one space van accessible, per 4.1.2 (5)(b).	020		
				per 4.1.2 (5)(b).		502.6		021		
019	1988	1	Back Lot	There is no accessible route from access aisles to			Remove walkway in front of space and reconstruct area to be level with			
				main entry without entering a vehicular lane of traffic.		502.3	parking lot surface. Construct a ramp from parking to walkway	021		
							provide an accessible route to covered entry.			

	1988						Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where			
020		1	Lobby	No visual strobe in area.		215.1	admitted patients are under the supervision of facility personnel.	N/A		
					H					
	1000						Remove obstruction, replace with similar item that protrudes less than			
021	1988	1	Lobby	Portable personal protection station protrudes 6 1/2" from wall.		204.1	4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	022		
				Tion wan.		001.2				
022	1988	1	Lobby	Strobe does not provide a clear or nominal white		215.1	install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	023		
			•	lense over bulb.			potocinon			
					\dashv					
023	1988	1	Lobby	Insufficient knee clearance of 24 3/4".		606.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5.	024		
					\dashv					
					Ħ					
	Year		Area of						Estimated	

#	Built	Floor	Condition	Condition	TC	ADAAG	Recommendation	Photo	Cost	Comments
024	1988	1	Radiology	Sign does not have braille.			Provide braille signage, per 4.30.	025		
			0,				3 3 71			
							install a 42" grap par aside the water closet at a neight of 33"-36" to			
							the center of the bar. If a 42" grab bar will not fit within the dimensions			
							of the existing space, then install the longest standard length bar that			
							will fit within the existing space, such that it does not protrude greater			
025	1988	1	Radiology	Grab bar on the side of the toilet is 36" in length.		604.5.1	than 54 inches from wall behind water closet.	026		
			Restroom	·		609.4		027		
							Install a 36" grab bar behind the water closet at a height of 33"-36" to			
							the center of the bar. If a 36" grab bar will not fit within the dimensions			
							of the space, then install the longest standard length bar that will fit			
026	1988	1	Radiology	Grab bar behind the toilet is only 24" in length.		604.5.2	within the existing space, not less than 24 inches in length.	026		
			Restroom			609.4		027		
							Reconfigure valve to wide side (including, if applicable, replacement of			
							flush tank), or install automatic flush device as an equivalent			
027	1988	1	Radiology	Flush valve not on wide side.		604.6	facilitation.	026		
			Restroom					027		
							Modify to make compliant, whether by moving toilet, moving partition			
028	1988	1	Radiology	Toilet bowl is 16 1/2" from side wall.	005	604.2	and/or wall so that toilet bowl is 16-19 inches from wall.	026		
			Restroom					027		
							Relocate the mirror to 40" in height to the reflective edge, per 4.19.6,			
029	1988	1	Radiology	Mirror at 48 1/2"AFF to bottom of reflective edge.		603.3	or install full-length mirror.	026		
			Restroom					027		

							Install ADA compliant strobes if and when replacing or rebuilding	1		
							existing fire alarm system. Strobes should be installed in general			
							public areas, including cafeterias, vending areas, retail pharmacies,			
							gift shops, chapels, public restrooms, lobbies, waiting rooms,			
							walkways and corridors, business office areas where the public is			
							normally invited (e.g., cashier or personnel office for receipt of			
							applications), conference rooms and classrooms open to the public,			
							and enclosed dressing rooms. Strobes should not be installed in			
							patient rooms (including restrooms in patient rooms), operating			
							rooms, surgical suites and preparation areas, recovery rooms, areas			
							where the patient is undergoing or recovering from anesthesia,			
							emergency department examination and treatment rooms, ICU rooms			
							and other special areas for admitted patients such as NICU or PACU,			
							blood draw and laboratory areas, imaging rooms and diagnostic			
							testing or procedure rooms, psychiatric wards generally, physical			
							therapy training and rehabilitation areas to the extent supervised by			
							medical personnel (except not if exercise areas or equipment are			
							available for use by the general public), and other areas where			
030	1988	1	Radiology	No visual strobe in area.		215.1	admitted patients are under the supervision of facility personnel.	N/A		
-			Restroom							
							Adjust closer to an opening force of 5lbf or less, and a closing speed			
							of no less than 3 seconds. If closer is not adjustable, replace with an			
							ADA-compliant closer. If a fire-rated door, adjust closer to be as light			
031	1988	1	West Side Women's	Door pressure is 11lbf.		404 2 9	as possible while still consistently closing and latching the door.	028		
			Restroom							
032	1988	1	West Side Women's	Sign is non-ADA type and is not properly located.		216.8	Provide signage with braille and the symbol of accessibility. These	028		
032	1300	-	Restroom	Sign is non-ADA type and is not properly located.		703.4.1	restrooms shall be identified as the accessible lobby restrooms.	020		
							Signage can be provided at east lobby restrooms directing to these			
							rooms.			
033	1988	1	West Side Women's	Sign does not have braille.		703.3	Provide braille signage, per 4.30.	028		
			Restroom							
034	1988	1	West Side Women's	Pull side of door only has 2" clear floor space on latch		404.1		029		
			Restroom	side.		404.2.4	pull side of door. Partitions will also need to be reconfigured,	030		
								031		
035	1988	1	West Side Women's	Lavatory hot water and drain pipes are exposed.		213 3 4	Provide pipe insulation on hot water pipe and drain pipe.	032		
	.000	<u> </u>	Restroom			606.5				
Item	Year		Area of						Estimated	
#	Built	Floor		Condition	TC	ADAAG	Recommendation Modify to make compliant, whether by moving toilet, moving partition	Photo	Cost	Comments
								1		
036	1988	1	West Side Women's	Toilet bowl is 32 1/2" from side wall.		604.2	and/or wall so that toilet bowl is 16-19 inches from wall.	033		
—			Restroom		-	-				

037 19	1988						Reconfigure valve to wide side (including, if applicable, replacement of flush tank), or install automatic flush device as an equivalent		
037 1:	1988								
037	1300		West Side Women's	Flush valve not on wide side.		604.6		033	
			Restroom	Flush valve not on wide side.		004.0	iacilitation.	033	
			Restroom						
							Install a 42 grap par aside the water closet at a neight of 33 -36 to		
							the center of the bar. If a 42" grab bar will not fit within the dimensions		
							of the existing space, then install the longest standard length bar that		
000			144 6: 1 . 144			00454	will fit within the existing space, such that it does not protrude greater	000	
038 19	1988	1	West Side Women's	Grab bar on the side of the toilet is 36" in length.		604.5.1	than 54 inches from wall behind water closet.	033	
			Restroom			609.4			
							Install ADA compliant strobes if and when replacing or rebuilding		
							existing fire alarm system. Strobes should be installed in general		
							public areas, including cafeterias, vending areas, retail pharmacies,		
							gift shops, chapels, public restrooms, lobbies, waiting rooms,		
							walkways and corridors, business office areas where the public is		
							normally invited (e.g., cashier or personnel office for receipt of		
							applications), conference rooms and classrooms open to the public,		
							and enclosed dressing rooms. Strobes should not be installed in		
							patient rooms (including restrooms in patient rooms), operating		
							rooms, surgical suites and preparation areas, recovery rooms, areas		
							where the patient is undergoing or recovering from anesthesia,		
							emergency department examination and treatment rooms, ICU rooms		
							and other special areas for admitted patients such as NICU or PACU,		
							blood draw and laboratory areas, imaging rooms and diagnostic		
							testing or procedure rooms, psychiatric wards generally, physical		
							therapy training and rehabilitation areas to the extent supervised by		
							medical personnel (except not if exercise areas or equipment are		
							available for use by the general public), and other areas where		
039 19	1988	1	West Side Women's	No visual strobe in area.		215.1	admitted patients are under the supervision of facility personnel.	N/A	
$oxed{oxed}$			Restroom						
$oxed{oxed}$									
040 19	1988	1	West Side Women's	Coat hook is 59 1/2" AFF.		308.2.1	Lower or provide additional hook, per 4.2.5 or 4.2.6.	031	
			Restroom			308.3.1			
041 19	1988	1	West Side Women's	No pull handle on pull side of the partition door.		604.8.	Install pull handle on pull side of door.	031	
 			Restroom			1.2			
\vdash				1		1.2			1
\vdash	- 1			 	\vdash				
042 4	1000	1	Most Cido Monio	Cign is non ADA type and is not properly !		246.0	Drovide signed with braille and the symbol of second 1995. These	024	
042 19	1988		West Side Men's	Sign is non-ADA type and is not properly located.	\vdash		Provide signage with braille and the symbol of accessibility. These	034	
			Restroom			103.4.1	restrooms shall be identified as the accessible lobby restrooms.		
$\vdash \!$					Ш		Signage can be provided at east lobby restrooms directing to these		
$oxed{oxed}$							rooms.		
043 19	1988	1	West Side Men's	Pull side of door only has 2" clear floor space on latch		404.1	Reconstruct drywall constructed wall to provide a minimum 18" on	034	
			Restroom	side.		404.2.4	pull side of door. Partitions will also need to be reconfigured,	035	
044 19	1988	1	West Side Men's	Lavatory hot water and drain pipes are exposed.		213.3.4	Provide pipe insulation on hot water pipe and drain pipe.	036	
			Restroom	,		606.5			

			l		T			1		
<u> </u>					1			 	 	
							Install a 42 grap par aside the water closet at a neight of 33 -36 to			
							the center of the bar. If a 42" grab bar will not fit within the dimensions			
							of the existing space, then install the longest standard length bar that			
1			l				will fit within the existing space, such that it does not protrude greater			
045	1988	1	West Side Men's	Grab bar on the side of the toilet is 36" in length.			than 54 inches from wall behind water closet.	037		
			Restroom			609.4				
							Install ADA compliant strobes if and when replacing or rebuilding			
							existing fire alarm system. Strobes should be installed in general			
							public areas, including cafeterias, vending areas, retail pharmacies,			
							gift shops, chapels, public restrooms, lobbies, waiting rooms,			
							walkways and corridors, business office areas where the public is			
							normally invited (e.g., cashier or personnel office for receipt of			
							applications), conference rooms and classrooms open to the public,			
							and enclosed dressing rooms. Strobes should not be installed in			
							patient rooms (including restrooms in patient rooms), operating			
							rooms, surgical suites and preparation areas, recovery rooms, areas			
							where the patient is undergoing or recovering from anesthesia,			
							emergency department examination and treatment rooms, ICU rooms			
							and other special areas for admitted patients such as NICU or PACU,			
							blood draw and laboratory areas, imaging rooms and diagnostic			
							testing or procedure rooms, psychiatric wards generally, physical			
							therapy training and rehabilitation areas to the extent supervised by			
							medical personnel (except not if exercise areas or equipment are			
							available for use by the general public), and other areas where			
			l a							
046	1988	1	West Side Men's	No visual strobe in area.		215.1	admitted patients are under the supervision of facility personnel.	N/A		
			Restroom		_					
					_					
					_					
0.45	1000			0						
047	1988	1	West Side Men's	Coat hook is 59 1/2" AFF.	1		Lower or provide additional hook, per 4.2.5 or 4.2.6.	038	├	
			Restroom		<u> </u>	308.3.1				
					1			<u> </u>	├	
					₩					
			A						Fathers 1	
Item	Year	Fla	Area of	On distan	T.C.	ADAAG	December detien	Dhati	Estimated	0
# 048	Built 1988	rioor	Condition West Side Men's	Condition No pull handle on pull side of the partition door.	IC	ADAAG	Recommendation Install pull handle on pull side of door.	Photo 038	Cost	Comments
046	1908			ino pui nanule on puil side of the partition door.	₩		· ·	USG	 	
			Restroom		<u> </u>	1.2		-	1	
					 					
					1			<u> </u>		
0.46	1000		M	0:		700.0	D. 11-1-211-21-21-21-21-21-21-21-21-21-21-2	000		
049	1988	1	Metronome Room and	Sign does not have braille.	<u> </u>	703.3	Provide braille signage, per 4.30.	039	1	
			Neuromuscular Rehab		<u> </u>					
					1					
_		_			_			_		

050	1988	1		No visual strobe in area.	215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A	
		-	Neuromuscular Rehab					
						Homovo obstruction, replace with similar item that protesides less than		
051	1988	1	Employee/Visitor	Suggestion box protrudes 6" from wall.	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	040	
			Dining		307.2			
052	1988	1	Employee/Visitor Dining	Strobe does not provide a clear or nominal white lense over bulb.	215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A	
			3				1	
052	1000	4	East Side Outrations	Sign doos not have braille	702.2	Provide braille signage, per 4.20	044	
053	1988	1	East Side Outpatient Registration	Sign does not have braille.	103.3	Provide braille signage, per 4.30.	041	<u> </u>

054	1988	1	East Side Outpatient Registration	No visual strobe in area.		215.1	Install ADA compliant strobes it and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A	
055	1988	1	East Side Outpatient Registration	Strobe does not provide a clear or nominal white lense over bulb.		215.1	install ADA compliant strobes it and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A	
056	1988	1	East Side Outpatient Registration	Suggestion box protrudes 6" from wall.		204.1 307.2	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	042	
057	1988	1	East Side Outpatient	Coat hook is 68 1/2" AFF.		308.2.1	Lower or provide additional hook, per 4.2.5 or 4.2.6.	043	
			Registration			308.3.1			
-					H				

							Install ADA compliant strobes if and when replacing or rebuilding			
							existing fire alarm system. Strobes should be installed in general			
							public areas, including cafeterias, vending areas, retail pharmacies,			
							gift shops, chapels, public restrooms, lobbies, waiting rooms,			
							walkways and corridors, business office areas where the public is			
							normally invited (e.g., cashier or personnel office for receipt of			
							applications), conference rooms and classrooms open to the public,			
							and enclosed dressing rooms. Strobes should not be installed in			
							patient rooms (including restrooms in patient rooms), operating			
							rooms, surgical suites and preparation areas, recovery rooms, areas			
							where the patient is undergoing or recovering from anesthesia,			
							emergency department examination and treatment rooms, ICU rooms			
							and other special areas for admitted patients such as NICU or PACU,			
							blood draw and laboratory areas, imaging rooms and diagnostic			
							testing or procedure rooms, psychiatric wards generally, physical			
							therapy training and rehabilitation areas to the extent supervised by			
							medical personnel (except not if exercise areas or equipment are			
050	1000	1	Outpotiont Cum	Stroke does not provide a clear or namical white		245.4	available for use by the general public), and other areas where	NI/A]	
058	1988	1	Outpatient Gym	Strobe does not provide a clear or nominal white lense over bulb.	+	215.1	admitted patients are under the supervision of facility personnel.	N/A		
				TOTIOC OVER DUID.	1	 				
							Install ADA compliant strobes if and when replacing or rebuilding			
							existing fire alarm system. Strobes should be installed in general			
							public areas, including cafeterias, vending areas, retail pharmacies,			
							gift shops, chapels, public restrooms, lobbies, waiting rooms,			
							walkways and corridors, business office areas where the public is			
							normally invited (e.g., cashier or personnel office for receipt of			
							applications), conference rooms and classrooms open to the public,			
							and enclosed dressing rooms. Strobes should not be installed in			
							and enclosed dressing rooms. Strobes should not be installed in			
							patient rooms (including restrooms in patient rooms), operating			
							patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas			
							patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia,			
							patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms			
							patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU,			
							patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic			
							patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical			
							patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by			
							patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are			
	4000		01/			045.4	patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where			
059	1988	1	Office and Storage	Strobe does not provide a clear or nominal white		215.1	patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where	N/A		
059	1988	11	Office and Storage	Strobe does not provide a clear or nominal white lense over bulb.		215.1	patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where	N/A		
059	1988	1	Office and Storage			215.1	patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where	N/A		
		1				215.1	patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where	N/A	Entiment	
Item	Year	1	Area of	lense over bulb.	TO		patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.		Estimated	Comments
		1 Floor 1		lense over bulb. Condition	TO	ADAAG	patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A Photo 044		Comments
Item #	Year Built	1 Flooi	Area of Condition	lense over bulb.	TO	ADAAG	patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel. Recommendation Provide signage, per 4.30. Do not designate this restroom as an	Photo		Comments
Item #	Year Built	1 Floor	Area of Condition East Side Men's	lense over bulb. Condition	TO	216.8	patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel. Recommendation Provide signage, per 4.30. Do not designate this restroom as an	Photo		Comments
Item #	Year Built	1 Floor	Area of Condition East Side Men's	lense over bulb. Condition	TC	216.8	patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel. Recommendation Provide signage, per 4.30. Do not designate this restroom as an accessible restroom if signage is provided to direct to west lobby	Photo		Comments
Item #	Year Built	1 Floor	Area of Condition East Side Men's	lense over bulb. Condition	TO	216.8	patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel. Recommendation Provide signage, per 4.30. Do not designate this restroom as an accessible restroom if signage is provided to direct to west lobby restrooms. See item 061.	Photo		Comments
Item #	Year Built	Flooi	Area of Condition East Side Men's	lense over bulb. Condition	TO	216.8	patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel. Recommendation Provide signage, per 4.30. Do not designate this restroom as an accessible restroom if signage is provided to direct to west lobby restrooms. See item 061.	Photo		Comments
Item #	Year Built	1 Floor	Area of Condition East Side Men's	lense over bulb. Condition	TO	216.8	patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel. Recommendation Provide signage, per 4.30. Do not designate this restroom as an accessible restroom if signage is provided to direct to west lobby restrooms. See item 061. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an	Photo		Comments
	Year Built 1988	Floor	Area of Condition East Side Men's Restroom	Condition Sign is non-ADA type and is not properly located.	TO	216.8 703.4.1	patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel. Recommendation	Photo 044		Comments
Item #	Year Built	Floor	Area of Condition East Side Men's Restroom East Side Men's	lense over bulb. Condition	TO	216.8 703.4.1	patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel. Recommendation Provide signage, per 4.30. Do not designate this restroom as an accessible restroom if signage is provided to direct to west lobby restrooms. See item 061. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an	Photo 044		Comments
	Year Built 1988	1	Area of Condition East Side Men's Restroom	Condition Sign is non-ADA type and is not properly located.	TO	216.8 703.4.1	patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel. Recommendation	Photo 044		Comments

	1 1	1			1	1	T	1	
062	1988	-1	East Side Men's	Push side of door only has 2" clear floor space on		404.1	Remove door latch to eliminate operation of door hardware upon entry	044	
002	1900		Restroom	latch side.		404.1		045	. +
-			Restroom	lateri side.	+	404.2.4	door. Signage may also be provided at entry directing to the	045	
							designated accessible lobby restrooms on west side of lobby.	047	
							designated accessible lobby restrooms on west side of lobby.	041	
063	1988	1	East Side Men's	Insufficient clear floor space of 36" in		604.3.1	Combine adjacent stalls to create floor space if plumbing codes allow,	049	
- 000	1000		Restroom	the designated accessible stall.	+	004.0.1	or provide proper signage at entry directing to the designated	050	
-			rtootroom	the designated desections stail.	+		accessible lobby restrooms on west side of lobby.	000	,
							accession lossy recircums on most side of lossy.		
064	1988	1	East Side Men's	Edge of the urinal is at a height of 24 1/2" AFF.		213.3.3	Relocate the urinal to a height of 17", per 4.18.2	049	
			Restroom			605.2	,		
							Reconfigure valve to wide side (including, if applicable, replacement of		
							flush tank), or install automatic flush device as an equivalent		
065	1988	1	East Side Men's	Urinal flush valve is at a height of 44 1/2" AFF.	006	604.6	facilitation.	049	,
			Restroom	3		605.4			
066	1988	1	East Side Men's	Stall door width is only 22".		604.3.1	Reconfigure door, per 4.13.	050	
			Restroom	·				051	
							Install a 36" grab bar behind the water closet at a height of 33"-36" to		
							the center of the bar. If a 36" grab bar will not fit within the dimensions		,
							of the space, then install the longest standard length bar that will fit		
067	1988	1	East Side Men's	Grab bar behind the toilet is only 24" in length.			within the existing space, not less than 24 inches in length.	050	
			Restroom			609.4		051	
							Install a 42" grap par aside the water closet at a neight of 33"-36" to		
							the center of the bar. If a 42" grab bar will not fit within the dimensions		
							of the existing space, then install the longest standard length bar that		,
									,
							will fit within the existing space, such that it does not protrude greater		,
068	1988	1	East Side Men's	Grab bar on the side of the toilet is 36" in length.		604.5.1	than 54 inches from wall behind water closet.	050	
<u> </u>	1		Restroom		-	609.4		051	
-					+	1			
							Modify to make compliant, whether by moving toilet, moving partition		
069	1988	1	East Side Men's	Toilet is 15 1/2" to seat top.		604.2		050	, [
009	1900		Restroom	Tollects 13 1/2 to seat top.	-	004.2	anu/or wan so that tollet bown is 10-13 inches from wall.	050	
<u> </u>			IVESTIONII		-	-		001	
-					+	1			
070	1988	1	East Side Men's	Lavatory hot water and drain pipes are exposed.		213 3 4	Provide pipe insulation on hot water pipe and drain pipe.	052	
0,0	1300	-	Restroom	Lavatory not water and drain pipes are exposed.	+	606.5		002	+
-					+	000.0			
1						1			

							Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where			
071	1988	1	East Side Women's	No visual strobe in area.		215.1		N/A		
			Restroom							
					<u> </u>					
Item	Year		Area of						Estimated	
#	Built	Floor	Condition	Condition	TC	ADAAG		Photo	Cost	Comments
072	1988	1	East Side Women's	Sign is non-ADA type and is not properly located.		216.8		053		
			Restroom			703.4.1				
							restrooms. See item 063.			
073	1988	1	East Side Women's Restroom	Door pressure is 10lbf.		404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door.	053		
0.71	1000		E . O. I. W.			10.1.1		0.1.1		
074	1988	1	East Side Women's	Push side of door only has 4" clear floor space on		404.1	Remove door latch to eliminate operation of door hardware upon entry	044		
			Restroom	latch side.	 	404.2.4	or reconfigure walls and relocate entry to provide 12" on push side of door. Signage may also be provided at entry directing to the	053 054		
		 			╁		designated accessible lobby restrooms on west side of lobby.	055		
							and a second second second on work old or loady.	500		
075	1988	1	East Side Women's	Pull side of door only has 9 1/2" clear floor space on		404.1	Possible load bearing walls or other obstructions on both sides of	044		
			Restroom	latch side.		404.2.4		053		
							the designated accessible lobby restrooms on west side of lobby.	054		
					<u> </u>			055		
070	4000	4	Foot Oids Wasser!	landing at all and land and a second of OCU in		004.0.1	Combine adiabate to the to another floor and if a local to the local t	050		
076	1988	1	East Side Women's	Insufficient clear floor space of 36" in the designated accessible stall.	├	o∪4.3.1	Combine adjacent stalls to create floor space if plumbing codes allow,	056 057		
			Restroom	the designated accessible Stall.	├	-	or provide proper signage at entry directing to the designated accessible lobby restrooms on west side of lobby.	057	-	
		-				1	accessible looply restrouting our west side or looply.	000		
077	1988	1	East Side Women's Restroom	Grab bar behind the toilet is only 24" in length and Grab bar on the side of the toilet is 36" in length.		604.5.1 604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	058		
				The second secon	t			l		

084 1988 1 Pool Sign does not have braille. 703.3 Provide braille signage, per 4.30. N/A 085 1988 1 Pool The edge of the reflecting pool does not have Not req Provide detectable warnings along pool edge, per 4.29.6 062		1		Г	T	1	1	T		1	1
1978 1 East Side Women's Resistroom APF. 1988 1 East Side Women's APF. 1988 2 East Side Women's APF. 1988 3 East Side Women's APF. 1988 1 East Side Women's APF. 1988 2 East Side Women's APF. 1988 3 East Side Women's APF. 1988 4 East Side Women's APF. 1988 5 East Side Women's APF. 1988 6 East Side Women's APF. 1988 7 East Side Women's APF. 1988 8 East Side Women's APF. 1988 8 East Side Women's APF. 1988 1 East Side Women's APF. 1988 2 East Side Women's APF. 1988 3 East Side Women's APF. 1988 1 East Side Women's APF. 1988 1 East Side Women's APF. 1988 2 East Side Women's APF. 1988 3 East Side Women's APF. 1988 4 East Side Women's APF. 1988 6 East Side Women's APF. 1988 6 East Side Women's APF. 1988 6 East Side Women's APF. 1988 7 East Side Women's APF. 1988 7 East Side Women's APF. 1988 8 East Side Women's APF. 1988 9 East Side Women's APF. 1988 9 East Side Women's APF. 1988 9 East Side Women's APF. 1988 1 East Side Women											
1988 1 East Side Women's The aids approach paper towel dispenser is 55 1/2 308.3.1 Lower the towel dispenser to a maximum height of 54" for a side 0.59 1988 1 East Side Women's The aids approach 1989 1 1	078	1988	1		Toilet is 15 1/2" to seat top.		604.4	, i	058		
Restroom AFF: Set Side Women's Set Side Women'			-	Restroom							
Restroom AFF. Set Side Women's Set Side Women'						+					
Restroom AFF. Set Side Women's Set Side Women'											
1 East Side Women's Lavatory hot water and drain pipes are exposed. 213.3.4 Provide pipe insulation on hot water pipe and drain pipe. 060 065 0665 0665 0666 0666 0666 0666	079	1988	1				308.3.1		059		
Restroom GOB. 5				Restroom	AFF.			approach.			
Restroom G06.5						-					
Restroom GOB. 5											
Restroom G06.5	080	1988	1	Fast Side Women's	Lavatory hot water and drain pines are exposed		213 3 4	Provide nine insulation on hot water nine and drain nine	060		
Install ADA compiant strobes if and when replacing or rebuilding existing file alarm system. Strobes should be installed in general public less controlled to installed in general public general public general public general public general public general public general general general public general general general public general gen	000	1300	<u> </u>		Lavatory not water and drain pipes are exposed.	1			000		
existing fire alarm system. Strobes should be installed in general public areas, including calleteries, ending areas, readil pharmacies, gift shops, chapels, public restrooms, lobbies, walling rooms, walkays and contriors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications of control of public and enclosed dressing rooms. Strobes should not be installed in patient rooms, conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms, conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms, conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms, conference rooms and classrooms on preventing the conference of recovering from an examination and treatment rooms, ICU rooms, surgical suites and preparation areas, recovery rooms, separating rooms, and other recovering rooms and disposation of recovering from an examination and treatment rooms, ICU rooms, surgical suites and preparation areas, recovery rooms, separating rooms, and patients and preparation areas, recovery rooms, separating rooms, and other recovery rooms, separating rooms, and recovery rooms, separating rooms, surgical suites and preparation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where available for use by the general public, and other areas where available for use by the general public, and other areas where available for use by the general public, and other areas where available for use by the general public, and other areas where available for use by the general public, and other areas where available for use by the general											
existing fire alarm system. Strobes should be installed in general public areas, including calleteries, ending areas, readil pharmacies, gift shops, chapels, public restrooms, lobbies, walling rooms, walkays and contriors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications of control of public and enclosed dressing rooms. Strobes should not be installed in patient rooms, conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms, conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms, conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms, conference rooms and classrooms on preventing the conference of recovering from an examination and treatment rooms, ICU rooms, surgical suites and preparation areas, recovery rooms, separating rooms, and other recovering rooms and disposation of recovering from an examination and treatment rooms, ICU rooms, surgical suites and preparation areas, recovery rooms, separating rooms, and patients and preparation areas, recovery rooms, separating rooms, and other recovery rooms, separating rooms, and recovery rooms, separating rooms, surgical suites and preparation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where available for use by the general public, and other areas where available for use by the general public, and other areas where available for use by the general public, and other areas where available for use by the general public, and other areas where available for use by the general public, and other areas where available for use by the general											
Restrooms Nature	081	1988	1		No visual strobe in area.		215.1	existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where			
Restrooms 1 Water Fountain by West Insufficient knee clearance of 24 1/2". 1 Restrooms 1 Rest											
1988 1 Water Fountain by West Insufficient knee clearance of 24 1/2". 606.2 Reconfigure fountain to provide 27" knee clearance, per 4.15.5. 061 Restrooms Item Year	082	1988	1		Signs do not have braille.		703.3	Provide braille signage, per 4.30.	N/A		
Restrooms				Restrooms							
Restrooms Item Year Area of Estimated # Built Floor Condition Condition TC ADAAG Recommendation Photo Cost Cor 084 1988 1 Pool Sign does not have braille. 703.3 Provide braille signage, per 4.30. N/A Pool The edge of the reflecting pool does not have Not req Provide detectable warnings along pool edge, per 4.29.6 062			1			1	1				
Restrooms											
# Built Floor Condition Condition TC ADAAG Recommendation Photo Cost Cor 084 1988 1 Pool Sign does not have braille. 703.3 Provide braille signage, per 4.30. N/A OBS 1988 1 Pool The edge of the reflecting pool does not have Not req Provide detectable warnings along pool edge, per 4.29.6 062	083	1988	1		Insufficient knee clearance of 24 1/2".		606.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5.	061		
# Built Floor Condition Condition TC ADAAG Recommendation Photo Cost Cor 084 1988 1 Pool Sign does not have braille. 703.3 Provide braille signage, per 4.30. N/A 085 1988 1 Pool The edge of the reflecting pool does not have Not req Provide detectable warnings along pool edge, per 4.29.6 062											
# Built Floor Condition Condition TC ADAAG Recommendation Photo Cost Cor 084 1988 1 Pool Sign does not have braille. 703.3 Provide braille signage, per 4.30. N/A 085 1988 1 Pool The edge of the reflecting pool does not have Not req Provide detectable warnings along pool edge, per 4.29.6 062	Item	Year		Area of						Estimated	
084 1988 1 Pool Sign does not have braille. 703.3 Provide braille signage, per 4.30. N/A 085 1988 1 Pool The edge of the reflecting pool does not have Not req Provide detectable warnings along pool edge, per 4.29.6 062	#	Built	Floor	Condition		TC			Photo		Comments
	084	1988	1	Pool	Sign does not have braille.	$oxedsymbol{oxedsymbol{oxedsymbol{oxedsymbol{\Box}}}$	703.3	Provide braille signage, per 4.30.	N/A		
	085	1988	1	Pool	The edge of the reflecting pool does not have		Not rea	Provide detectable warnings along pool edge, per 4.29.6	062		
ı ı ı quetectable warnings. I 2010 I I I I		1	Ė		detectable warnings.		2010	, , , , , , , , , , , , , , , , , , ,			

					ADA		1	
086	1988	1	Men's Locker by Pool	Sign is non-ADA type and is not properly located.		Provide signage, per 4.30.	063	
-					703.4.1			+
087	1988	1	Men's Locker by Pool	Pull side of door only has 2" clear floor space on latch	404.1	Remove cabinets and small wall to provide a minimum 18" on pull side	063	
				side.	404.2.4		064	
						Install ADA compliant strobes if and when replacing or rebuilding		
						existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where		
880	1988	1	Men's Locker by Pool	No visual strobe in area.	215.1	admitted patients are under the supervision of facility personnel.	N/A	
089	1988	1	Men's Locker by Pool	Insufficient knee clearance of 26 3/4".	606.2	Cut lower lip of counter to allow for a minimum of 29" knee clearance	065	
						at the bottom of the apron.		
090	1988	-1	Men's Locker by Pool	Lavatory hot water and drain pipes are exposed.	212.2.4	Provide pipe insulation on hot water pipe and drain pipe.	065	
090	1900	-	INICITS LUCKET BY PUOL	Lavatory not water and draff pipes are exposed.	606.5		000	
 					300.3		1	
091	1988	1	Men's Locker by Pool	Lavatory faucet does not provide lever type hardware.	606.4	Provide a faucet which complies with 4.27.4.	065	
092	1988	1	Men's Locker by Pool	Toilet bowl is 21 1/2" from side wall.	604.2	Modify to make compliant, whether by moving toilet, moving partition and/or wall so that toilet bowl is 16-19 inches from wall.	066	
	1223		, ,, , , , , , , , , , , , , , , ,				1	

093	1988	1	Men's Locker by Pool Men's Locker by Pool Men's Locker by Pool	Grab bar on the side of the toilet is 36" in length. Insufficient clear floor space of 48" in the designated accessible stall. Insufficient shower seat size and location.		604.5.1 609.4 604.3.1	Install a 42" grab bar aside the water closet at a neight of 33"-35" to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater than 54 inches from wall behind water closet. Reconfigure partitions to provide a 32" door to left of toilet, move partitions out approx. 3", provide ceiling mount for partitions and remove floor mount. Wall mounted toilet may be needed to create 60" turning radius. Another option is to make restroom single use. Provide a shower seat per § 4.21.3, or make a portable seat available and train medical personnel to provide assistance when necessary or required, or provide a wheelchair accessible shower and shower wheelchair.	066 066 067 068		
			•			610.1		070		
					+					
Item #	Year Built	Floor	Area of Condition	Condition	TC	ADAAG	Recommendation	Photo	Estimated Cost	Comments
#	Duiit	FIOOI	Condition	Condition	10	ADAAG	Recommendation	FIIOLO	COSI	Comments
096	1988	1	Men's Locker by Pool	Grab bars in shower area are not properly		608.3	Install cross bar at height not less than 80 inches above finished floor.	069		
				located.				070		
097	4000	-	Marana I adamba	Circuit and ADA transport is not appropriate in the		040.0	Devide signature and 4.00	071		
097	1988	1	Women's Locker by Pool	Sign is non-ADA type and is not properly located.		703.4.1	Provide signage, per 4.30.	071		
098	1988	1	Women's Locker by Pool	No visual strobe in area.		215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A		
099	1988	1	Women's Locker by	Insufficient knee clearance of 26 1/2".		606.2	Relocate the lavatory to allow for a minimum of 29" knee clearance	072		
			Pool				at the bottom of the apron.			
				1	1					

						ı	T		1	
					<u> </u>					
100	1988	-1	Women's Locker by	Lavatory hot water and drain pipes are exposed.		212 2 4	Provide pipe insulation on hot water pipe and drain pipe.	072		
100	1900	-	Pool	Lavatory not water and drain pipes are exposed.	-	606.5		072		
			F001		-	000.5				
					1					
					<u> </u>					
101	1988	-1	Women's Locker by	Lavatory faucet not operable, per 4.19.5.		606.4	Provide a faucet which complies with 4.27.4.	072		
101	1900	-		Lavatory faucet not operable, per 4.19.5.	 	606.4	Provide a faucet which compiles with 4.27.4.	072		
			Pool		1					
					_					
					-					
					<u> </u>		Market to an also associated wheels are significant and a second significant size.			
		_					Modify to make compliant, whether by moving toilet, moving partition			
102	1988	1	Women's Locker by	Toilet bowl is 21 1/2" from side wall.	<u> </u>	604.2	and/or wall so that toilet bowl is 16-19 inches from wall.	073		
			Pool		<u> </u>					
							Install a 42" grap par aside the water closet at a neight of 33"-36" to			
							the center of the bar. If a 42" grab bar will not fit within the dimensions			
							of the existing space, then install the longest standard length bar that			
							will fit within the existing space, such that it does not protrude greater			
103	1988	1	Women's Locker by	Grab bar on the side of the toilet is 36" in length.		604.5.1	than 54 inches from wall behind water closet.	073		
			Pool	g		609.4				
					1				t	
104	1988	1	Women's Locker by	Insufficient clear floor space of 54" in the designated	1	604 3 1	Move partitions out approx. 7", provide ceiling mount for partitions and	073		
104	1900	-	Pool	accessible stall.	-	004.3.1	remove floor mount. Wall mounted toilet may be needed to create	073		
			P001	accessible stall.	<u> </u>	-	60" turning radius. Another option is to make restroom single use.	074		
					1		turning radius. Another option is to make restroom single use.	075		
					<u> </u>			076		
405	1000			D 4111 1 1 1 2 2 4 4 9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		0010				
105	1988	1	Women's Locker by	Partition door opening is 30 1/2" in width.	<u> </u>	604.8.	Increase door size to 32" when partitions are relocated.	074		
			Pool			1.2		075		
								076		
106	1988	1	Women's Locker by	Coat hook is 59" AFF.			Lower or provide additional hook, per 4.2.5 or 4.2.6.	N/A		
			Pool			308.3.1				
107	1988	2	Elevators	The emergency phone door does not have a pull		205.1	Provide pull handle, per 4.27.	077		
				handle.						
									ĺ	
Item	Year		Area of						Estimated	
#	Built	Floor	Condition	Condition	TC	ADAAG	Recommendation	Photo	Cost	Comments
π	Junt	. 1001	Condition	Condition	1.0	ADAAG	Recommendation Remove obstruction, replace with similar item that protrudes less than		OUSE	Comments
					1	1	4" from the wall, move the item off of the accessible route, raise to			
							above 80" AFF, or install a cane-detectible element with a leading			
108	1988	В	Work Able	P.P.E. protrudes 5 1/2" from wall.		204.1		N/A		
100	1900	ь	WOLK ADIC	r.r.L. protidues 5 1/2 Horri wall.	1	307.2	cage at or below 21 All.	IN/A		
			ı		₩	301.2				
					<u> </u>					
					L					
160	1000					705 1 -		0=2		
109	1988	В	Work Able-	Sign is located to left of door, not latch side of		703.4.2	Relocate signage to latch side of door, per 4.30.	078		
109	1988	В	Work Able- Women's Restroom	Sign is located to left of door, not latch side of opening.		703.4.2	Relocate signage to latch side of door, per 4.30.	078		
109	1988	В				703.4.2	Relocate signage to latch side of door, per 4.30.	078		
109	1988	В				703.4.2	Relocate signage to latch side of door, per 4.30.	078		

110	1988	В	Work Able- Women's Restroom	Door pressure is 7lbf.		404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door.	078	
111	1988	В	Work Able- Women's Restroom	Lavatory too high at 34 1/2" to the rim.		606.3	Relocate the lavatory to 34" in height to the rim, per 4.19.2.	079	
			Women's Restroom						
							Relocate the mirror to 40" in height to the reflective edge, per 4.19.6,		
112	1988	В	Work Able-	Mirror at 43 1/2"AFF to bottom of reflective edge.		603.3	or install full-length mirror.	079	
- 112	1000		Women's Restroom	William at 40 1/2 / 11 to bottom of following edge.		000.0	or motern rem to right minion	010	
113	1988	В	Work Able- Women's Restroom	No visual strobe in area.		215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A	
114	1988	В	Work Able-	Coat hook is 60 1/2" AFF.			Lower or provide additional hook, per 4.2.5 or 4.2.6.	079	
			Men's Restroom		\vdash	308.3.1			
115	1988	В	Work Able- Men's Restroom	Door pressure is 7lbf.		404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door.	078	
					H				
116	1988	В	Work Able-	Lavatory too high at 34 1/2" to the rim.		606.3	Relocate the lavatory to 34" in height to the rim, per 4.19.2.	080	
			Men's Restroom	- ¥			¥		
					igspace				
		l							

117 1	1988	В	Work Able-	Mirror at 43 1/2"AFF to bottom of reflective edge.			Relocate the mirror to 40" in height to the reflective edge, per 4.19.6,			
117 1	1988	В		Mirror at 42 1/2" A EE to bottom of reflective edge						
	.000					603.3	or install full-length mirror.	080		I
			Men's Restroom	miner at 10 1/2 / ii i to bottom or remodito dager		000.0	J. Harton van Grigorium Gr	000		
							Install ADA compliant strobes if and when replacing or rebuilding			
							existing fire alarm system. Strobes should be installed in general			1
1							public areas, including cafeterias, vending areas, retail pharmacies,			1
							gift shops, chapels, public restrooms, lobbies, waiting rooms,			I
							walkways and corridors, business office areas where the public is			1
							normally invited (e.g., cashier or personnel office for receipt of			1
							applications), conference rooms and classrooms open to the public,			I
							and enclosed dressing rooms. Strobes should not be installed in			1
							patient rooms (including restrooms in patient rooms), operating			1
							rooms, surgical suites and preparation areas, recovery rooms, areas			1
							where the patient is undergoing or recovering from anesthesia,			1
							emergency department examination and treatment rooms, ICU rooms			1
							and other special areas for admitted patients such as NICU or PACU,			1
							blood draw and laboratory areas, imaging rooms and diagnostic			1
							testing or procedure rooms, psychiatric wards generally, physical			1
							therapy training and rehabilitation areas to the extent supervised by			1
							medical personnel (except not if exercise areas or equipment are			ı
							available for use by the general public), and other areas where			ı
118 1	1988	В	Work Able-	No visual strobe in area.		215.1	admitted patients are under the supervision of facility personnel.	N/A		I
			Men's Restroom							
					<u> </u>					
							Remove obstruction, replace with similar item that protrudes less than			
							4" from the wall, move the item off of the accessible route, raise to			1
							above 80" AFF, or install a cane-detectible element with a leading			1
119 1	1988	2	Hallways	Portable personal protection station protrudes 6 1/2"		204.1	edge at or below 27" AFF.	N/A		1
				from wall.		307.2				
	Year		Area of	2	!				Estimated	
# B	Built	Floor	Condition	Condition	TC	ADAAG	Recommendation Remove obstruction, replace with similar item that protrudes less than	Photo	Cost	Comments
							4" from the wall, move the item off of the accessible route, raise to			1
							above 80" AFF, or install a cane-detectible element with a leading			1
120 1	1988	2	Hallways	Suggestion box protrudes 6" from wall.		204.1	edge at or below 27" AFF.	081		1
120	1300		Tidiiways	buggestion box protruces of from wall.		307.2	cage at or below 27 Arri.	001		
-+						007.2		1		
-										
121 1	1988	2	Room 216- Private	Sign does not have braille.		703.3	Provide braille signage, per 4.30.	082		
-								1		i
					<u> </u>					
122 1	1988	2	Room 216- Private	Television is unable to provide closed captioning.		28 CED	Replace existing TV with a closed caption compatible TV.	083		
122	1300		Noom 210- Private	relevision is unable to provide closed captioning.	+-	36.303	пъергасе ехіонну ту мінта стооей сарноп сотпранов ту.	003		<u> </u>
						30.303				 I
-+										
	1988	2	Room 216- Private	Blind controls at a height of 70 1/2" for forward reach		205.1	Extend the controls to a height of 48", per 4.2.5.	084		1
123 1						308.2.1				
123					_	300.2.1				

	1			T	1	1		1	1	
124	1988	2	Room 216- Private	Push side of door only has 2" clear floor space on	1	404.1	Reverse the latch and hinge side so door swings from the opposite	085		
127	1000		TROUTE TO THIVE	latch side.	1		side of frame.	086		
				idion side.	1	101.2.1	olde of Halife.	000		
125	1988	2	Room 216- Private	Coat hook is 70 1/2" AFF.		308 2 1	Lower or provide additional hook, per 4.2.5 or 4.2.6.	086		
120	1000		TROUTE TO THIVE	Coat Hook is 70 1/2 7411.	1	308.3.1	Lower of provide additional floors, per 4.2.0 or 4.2.0.	000		
						000.0.1				
							Install a 42" grap par aside the water closet at a neight of 33"-36" to			
							the center of the bar. If a 42" grab bar will not fit within the dimensions			
							of the existing space, then install the longest standard length bar that			
							will fit within the existing space, such that it does not protrude greater			
126	1988	2	Room 216- Private	Crob har an the side of the tailet is 24" in length and		CO4 E 4	than 54 inches from wall behind water closet.	087		
120	1900		Room 216- Private	Grab bar on the side of the toilet is 24" in length and	-		than 54 inches from wall bening water closet.	067		
				there is not a grab bar behind the toilet.		604.5.2				
	 		 		-	1		}		
					\vdash					
							Reconfigure valve to wide side (including, if applicable, replacement of			
			ĺ		1	1				
		_	5 040 5				flush tank), or install automatic flush device as an equivalent			
127	1988	2	Room 216- Private	Flush valve at a height of 51"		604.6	facilitation.	087		
							Relocate the mirror to 40" in height to the reflective edge, per 4.19.6,			
128	1988	2	Room 216- Private	Mirror at 41 1/2"AFF to bottom of reflective edge.		603.3	or install full-length mirror.	880		
							Provide a shower seat per § 4.21.3, or make a portable seat available			
							and train medical personnel to provide assistance when necessary or			
							required, or provide a wheelchair accessible shower and shower			
129	1988	2	Room 216- Private	No wall mounted seat in shower area.		608.4	wheelchair.	089		
						610.1				
130	1988	2	Room 217- Semi Private	Sign does not have braille.		703.3	Provide braille signage, per 4.30.	N/A		
131	1988	2	Room 217- Semi Private	Television is unable to provide closed captioning.		28 CFR	Replace existing TV with a closed caption compatible TV.	N/A		
						36.303				
Item	Year		Area of						Estimated	
#	Built	Floor		Condition	TC	ADAAG	Recommendation	Photo		Comments
132	1988			Blind controls at a height of 70 1/2" for forward reach	T		Extend the controls to a height of 48", per 4.2.5.	N/A		
				<u> </u>		308.2.1				
			1			†			i	
133	1988	2	Room 217- Semi Private	Push side of door only has 2" clear floor space on		404.1	Reverse the latch and hinge side so door swings from the opposite	N/A		
	1			latch side.			side of frame.			
			1							

					$\overline{}$				
134	1988	2	Room 217- Semi Private	Coat hook is 70 1/2" AFF.	30	08.2.1	Lower or provide additional hook, per 4.2.5 or 4.2.6.	N/A	
						08.3.1			
							Install a 42" grap par aside the water closet at a height of 33"-36" to		
					1		the center of the bar. If a 42" grab bar will not fit within the dimensions		i
					1		of the existing space, then install the longest standard length bar that		
					1		will fit within the existing space, such that it does not protrude greater		
135	1988	2	Room 217- Semi Private	Grab bar on the side of the toilet is 24" in length and	60)4.5.1	than 54 inches from wall behind water closet.	090	
.00	.000	_	Treesing 217 Committee	there is not a grab bar behind the toilet.		4.5.2		000	
				there is not a grap bar bermita the tellet.	- 00	1.0.2			
					-				
							Reconfigure valve to wide side (including, if applicable, replacement of		
					ı I		flush tank), or install automatic flush device as an equivalent		
136	1988	2	Poom 217- Sami Brigata	Flush valve at a height of 51"		04.6	facilitation.	090	•
130	1908		Noun 217- Seini Private	Flush valve at a neight of 51	<u> </u>	0.40	Iaulialiuti.	090	
				 	$-\!\!\!\!+\!\!\!\!-$				
	-			 	\vdash				
					\vdash				
					\leftarrow		Pologoto the mirror to 40" in height to the reflective edge === 4.40 C		
46-	4000	_	D 047 0	Managed Ad A/OIIA FE to Lots of the state of	ı 1 .		Relocate the mirror to 40" in height to the reflective edge, per 4.19.6,	00.	
137	1988	2	Room 217- Semi Private	Mirror at 41 1/2"AFF to bottom of reflective edge.	6	03.3	or install full-length mirror.	091	
					$oldsymbol{\sqcup}$				
					\vdash				
					$oldsymbol{\sqcup}$				
							V 4 1/4 1		
					1		Provide a shower seat per § 4.21.3, or make a portable seat available		ļ
					1		and train medical personnel to provide assistance when necessary or		ļ
					1		required, or provide a wheelchair accessible shower and shower		ļ
138	1988	2	Room 217- Semi Private	No wall mounted seat in shower area.		08.4	wheelchair.	N/A	
					6	10.1			
139	1988	2	OT Eye Testing Area	Sign does not have braille.	7/	03.3	Provide braille signage, per 4.30.	N/A	
							Install ADA compliant strobes if and when replacing or rebuilding		
					i 1		existing fire alarm system. Strobes should be installed in general		
					i 1		public areas, including cafeterias, vending areas, retail pharmacies,		ļ
					i 1		gift shops, chapels, public restrooms, lobbies, waiting rooms,		ļ
					ı I		walkways and corridors, business office areas where the public is		
					ı l		normally invited (e.g., cashier or personnel office for receipt of		
					ı I		applications), conference rooms and classrooms open to the public,		
					ı I				
					i 1		and enclosed dressing rooms. Strobes should not be installed in		
					i 1		patient rooms (including restrooms in patient rooms), operating		ļ
					i 1		rooms, surgical suites and preparation areas, recovery rooms, areas		
					ı I		where the patient is undergoing or recovering from anesthesia,		
					i 1		emergency department examination and treatment rooms, ICU rooms		
					i 1		and other special areas for admitted patients such as NICU or PACU,		
					ı I		blood draw and laboratory areas, imaging rooms and diagnostic		
					i 1		testing or procedure rooms, psychiatric wards generally, physical		
					i 1		therapy training and rehabilitation areas to the extent supervised by		
					i 1				
		1	1	i	. 1		medical personnel (except not if exercise areas or equipment are	1	
	l			l I	1		La construir de la construir d		
140	1988		OT Eye Testing Area	No visual strobe in area.	ļ		available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A	ĺ

			1			1	1			
					<u> </u>					
141	1988	2	OT Eye Testing Area	Door pressure is 12lbf.		404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door.	092		
142	1988	2	OT Eye Testing Area	Pull side of door only has 8" clear floor space on latch		404.1	Remove door or provide power door opener.	092		
				side.		404.2.4	· · · · ·			
	<u> </u>									
Item	Year		east restrooms and wes inpatient gym do not hav	t restrooms have doors that swing into the restrooms of re clear floor space concerns and are approximately 70°	bstru ' awa	ucting the ay from th	en's and women's restrooms. The inpatient gym has 2 unisex restroom clear floor space, which will not allow a 60" turning radius. The unisex re e east restrooms. Signage may be provided at the east restrooms and ations to be followed if all restrooms are to be modified for compliance.	estroom	s at the	
#		Floor		Condition	TC	ADAAG	Recommendation	Dhoto		Commonto
	1988	Floor 2	Condition East Men's Restroom	Signs are located on door, not latch side of opening.	10			Photo	Cost	Comments
						1 702 4 4	Delegate signage to letch side of door, per 4.20			
143	1900		Last Men's Restroom	Signs are located on door, not latch side of opening.			Relocate signage to latch side of door, per 4.30.	093		
143	1900		Last Well's Nestroom	Signs are located on door, not laten side or opening.		703.4.1 703.4.2		093 094		
143	1900	2	Last Well's Nestroull	Signs are located on door, not fatch side or opening.						
143	1900	2	Last Well's Nestroom	Signs are located on door, not laten side or opening.						
						703.4.2		094		
143	1988		East Men's Restroom	Sign does not have braille.		703.4.2				
						703.4.2		094		
						703.4.2		094		
						703.4.2		094		
	1988	2				703.4.2		094		
144	1988	2	East Men's Restroom	Sign does not have braille.		703.4.2	Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light	094		
144	1988	2	East Men's Restroom	Sign does not have braille.		703.4.2	Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light	094		
144	1988	2	East Men's Restroom East Men's Restroom	Sign does not have braille. Door pressure is 10lbf.		703.4.2	Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door.	094		
144	1988	2	East Men's Restroom	Sign does not have braille. Door pressure is 10lbf. Door swings into restroom, obstructing the clear floor		703.4.2 703.3 404.2.9	Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space.	094		
144	1988	2	East Men's Restroom East Men's Restroom	Sign does not have braille. Door pressure is 10lbf.		703.4.2	Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches	094 094 094 093 093		
144	1988	2	East Men's Restroom East Men's Restroom	Sign does not have braille. Door pressure is 10lbf. Door swings into restroom, obstructing the clear floor		703.4.2 703.3 404.2.9	Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space.	094		
144	1988	2	East Men's Restroom East Men's Restroom	Sign does not have braille. Door pressure is 10lbf. Door swings into restroom, obstructing the clear floor		703.4.2 703.3 404.2.9	Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches	094 094 094 093 093		
144	1988	2	East Men's Restroom East Men's Restroom	Sign does not have braille. Door pressure is 10lbf. Door swings into restroom, obstructing the clear floor		703.4.2 703.3 404.2.9 604.8 1.2	Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches	094 094 094 094 093 094 095		
144	1988	2	East Men's Restroom East Men's Restroom East Men's Restroom	Sign does not have braille. Door pressure is 10lbf. Door swings into restroom, obstructing the clear floor space.		703.4.2 703.3 404.2.9 604.8 1.2	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches automatically. See note above item #143 of this report. Install a 42 grab bar aside the water closet at a neight of 33-36 to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater	094 094 094 094 093 094 095		

testal a 36° grab bar behind the valer close at a height of 33°-36° to be center of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the dimensional content of the bar. It a 36° grab bar will not fix within the calculation of the bar. It a 36° grab bar will not fix within the calculation of the bar. It a 36° grab bar will not fix within the calculation of the bar. It a 36° grab bar will not fix within the calculation of the bar. It a 36° grab bar will not fix within the calculation of the bar. It a 36° grab bar will not fix within the calculation of the bar. It a 36° grab bar will not fix within the calculation of the bar. It a 36° grab bar will not fix will not fix within the calculation of the bar. It a 3						_					
190 1988 2 Bast Man's Restroom Mirror at 48 1/2" AFF to bottom of reflective edge. 1903.3 or install full-length mirror. 1971 19	148	1988	2	East Men's Restroom	Grab bar behind the toilet is only 24" in length.			the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit			
approach. Second Content of Co	149	1988	2	East Men's Restroom	Mirror at 48 1/2"AFF to bottom of reflective edge.		603.3		097		
1988 2 East Men's Restroom Toilet is 15 1/2" to seat top. 60.44 the top of the toilet seat, or install a riser as an equivalent facilitation. 096	150	1988	2	East Men's Restroom	The forward approach soap dispenser is 50" high.		308.2.1		097		
existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashine of presented office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the public sand enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the public and enclosed dressing rooms. Strobes should not be installed in patient surgical suites and preparation areas, recovery rooms, areas where the public and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient surd as NICU TOOMS, and enclosed dressing rooms. Strobes should not be installed in patient some strong from anesthesia, emergency department examination and treatment rooms, ICU rooms and other areas and distinct such as NICU TOOMS and other areas and distinct such as NICU TOOMS and other areas where the public, and enclosed dressing rooms, surgical suites and preparation areas, recovery rooms, areas where the public, and enclosed dressing rooms, and enclosed dressing rooms and classrooms open to the public, and enclosed dressing rooms and disapposite testing or procedure rooms, areas where the public and enclosed the patients and enclosed and enclosed dressing rooms and disapposite testing or procedure rooms, areas where the public and enclosed the patients and enclosed and enclosed the patients and enclosed the p	151	1988	2	East Men's Restroom	Toilet is 15 1/2" to seat top.		604.4		096		
existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the public sand enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the public and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the public and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), including restrooms, areas where the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms, location areas or displaying rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms, location and restrooms, including restrooms, openating rooms, sugical suites and preparation areas, recovery rooms, areas where the public, and enclosed dressing rooms. Strobe should not be restrooms, location and restrooms, locati						E					
Restroom 098	152	1988	2	East Men's Restroom	No visual strobe in area.		215.1	existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where	N/A		
Restroom	_										
#BuiltFloorConditionConditionTCADAAGRecommendationPhotoCostCom15419882East Women'sSign does not have braille.703.3Provide braille signage, per 4.30.093	153	1988	2		Signs are located on door, not latch side of opening.		703.4.2	Relocate signage to latch side of door, per 4.30.			
#BuiltFloorConditionConditionTCADAAGRecommendationPhotoCostCom15419882East Women'sSign does not have braille.703.3Provide braille signage, per 4.30.093	Hom	Veer		Area of						Estimated	
154 1988 2 East Women's Sign does not have braille. 703.3 Provide braille signage, per 4.30. 093			Floor		Condition	TC	ADAAG	Pecommendation	Photo		Comments
						10				COSt	Comments
090		1000			e.g., accomotinate braine.	\vdash	7 00.0	Torras Stame Signago, por 1.00.			
			1	1 10011 00111	I .	—	1		000		

	г т		1				T		
155	1988	2	East Women's Restroom	Door pressure is 14lbf.		404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door.	093 098	
156	1988	2	East Women's	Door swings into restroom, obstructing the clear floor		604.8		093	
			Restroom	space.		1.2	Door will also require a power opener if the door handle latches	098	
							automatically. See note above item #143 of this report.	099	
							Install a 42 grap par aside the water closet at a neight of 33 -36 to		
157	1988	2	East Women's Restroom	Grab bar on the side of the toilet is 32" in length.		604.5.1 609.4	the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater than 54 inches from wall behind water closet.	100	
158	1988	2	East Women's Restroom	Grab bar behind the toilet is only 24" in length.		604.5.2 609.4	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	100	
			restroom			000.4			
159	1988	2	East Women's	Mirror at 48 1/2"AFF to bottom of reflective edge.		603.3	Relocate the mirror to 40" in height to the reflective edge, per 4.19.6, or install full-length mirror.	101	
			Restroom						
160	1000	2	Cost Momenta	The forward approach according approach is 50" high		200.2.4	Lower the seen dispenses to a maximum height of 40" for a farward	101	
160	1988	2	East Women's Restroom	The forward approach soap dispenser is 50" high.	-	ა∪8.∠.1	Lower the soap dispenser to a maximum height of 48" for a forward approach.	101	
			IVE91100111				αργιναση.		
					-+				
161	1988	2	East Women's Restroom	Toilet is 15 1/2" to seat top.		604.4	Replace the water closet with one that is between 17"-19" in height to the top of the toilet seat, or install a riser as an equivalent facilitation.	100	
162	1988	2	East Women's	Flush control is not on wide side.		604.6	Reconfigure valve to wide side (including, if applicable, replacement of flush tank), or install automatic flush device as an equivalent facilitation.	101	
			Restroom						

163	1988	2	East Women's	No visual strobe in area.		215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A		
			Restroom		1					
164	1988	2	Water Cooler by East	Insufficient knee clearance of 24 1/2".		606.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5.	102		
104	1300		Restrooms	Insunicient knee clearance of 24 1/2 .		000.2	reconlingure fountain to provide 27 knee clearance, per 4.15.5.	102		
165	1988	2	Dining Room	Strobe does not provide a clear or nominal white lense over bulb.		215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A		
				nonico ever build.	\vdash	1	 			
Item	Year		Area of						Estimated	
#		Floor	Condition	Condition	тс	ADAAG		Photo	Cost	Comments
166	1988		Inpatient Gym	Sign does not have braille.			Provide braille signage, per 4.30.	N/A		
					1					
					\vdash	1	 			

167	1988	2	Inpatient Gym	Portable personal protection station protrudes 6 1/2" from wall.	204 307		N/A	
168	1988	2	Inpatient Gym-	Sign is non-ADA type and is not properly located.		8 Provide signage, per 4.30.	103	
			East Unisex Restroom		703.4	1		
						Relocate the mirror to 40" in height to the reflective edge, per 4.19.6,		
169	1988	2	Inpatient Gym- East Unisex Restroom	Mirror at 48 1/2"AFF to bottom of reflective edge.	603	3 or install full-length mirror.	104	
			East Unisex Restroom					
170	1988	2	Inpatient Gym- East Unisex Restroom	Grab bar on the side of the toilet is 24" in length.	604.	the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater than 54 inches from wall behind water closet.	104	
171	1988	2	Inpatient Gym- East Unisex Restroom	Grab bar behind the toilet is only 24" in length.	604. 609		104	
172	1988	2	Inpatient Gym- East Unisex Restroom	Flush valve not on wide side.	604	Reconfigure valve to wide side (including, if applicable, replacement of flush tank), or install automatic flush device as an equivalent facilitation.	104	
173	1988	2	Inpatient Gym-	Sign is non-ADA type and is not properly located.	216	8 Provide signage, per 4.30.	105	
113	1300		West Unisex Restroom	organis non-ADA type and is not properly located.	703.4		100	
					1 20.1			
						Relocate the mirror to 40" in height to the reflective edge, per 4.19.6,		
174	1988	2	Inpatient Gym- West Unisex Restroom	Mirror at 48 1/2"AFF to bottom of reflective edge.	603	or install full-length mirror.	106	
							1	
175	1988	2	Inpatient Gym- West Unisex Restroom	Grab bar on the side of the toilet is 24" in length.	604.		106	
					003	·	1	
			l	I	<u> </u>	I	11	

			ı	T		1	T		1 1	
					<u> </u>					
					<u> </u>					
							Install a 36" grab bar behind the water closet at a height of 33"-36" to			
							the center of the bar. If a 36" grab bar will not fit within the dimensions			
							of the space, then install the longest standard length bar that will fit			
176	1988	2	Inpatient Gym-	Grab bar behind the toilet is only 24" in length.		604.5.2	within the existing space, not less than 24 inches in length.	106		
			West Unisex Restroom			609.4				
							Remove obstruction, replace with similar item that protrudes less than			
							4" from the wall, move the item off of the accessible route, raise to			
							above 80" AFF, or install a cane-detectible element with a leading			
477	4000	_	Liellenene en Mant Cida	Destable acceptance station at the control of CA/OII		0044		N/A		
177	1988	2	Hallways on West Side	Portable personal protection stations protrude 6 1/2"	<u> </u>	204.1	edge at or below 27" AFF.	IN/A		
				from wall.	<u> </u>	307.2				
Item	Year		Area of						Estimated	
#	Built	Floor	Condition	Condition	TC	ADAAG	Recommendation	Photo	Cost	Comments
				- Condition	Η,	,,,,,,,,,	Recommendation Remove obstruction, replace with similar item that protrudes less than		5 55.	••••••
							4" from the wall, move the item off of the accessible route, raise to			
							above 80" AFF, or install a cane-detectible element with a leading			
178	1988	2	Hallways on West Cide	Suggestion box protrudes 6 1/4" from wall.		204.4		N/A		
178	1988		Hallways on West Side	Suggestion box protrudes 6 1/4 from wall.	1	204.1	euge at 01 below 21 AFF.	IN/A		
					<u> </u>	307.2				
					_					
					<u> </u>					
179	1988	2	Rooms 227 & 232	Sign does not have braille.		703.3	Provide braille signage, per 4.30.	N/A		
			Semi Private							
180	1988	2	Rooms 227 & 232	Television is unable to provide closed captioning.			Replace existing TV with a closed caption compatible TV.	N/A		
			Semi Private			36.303				
181	1988	2	Rooms 227 & 232	Blind controls at a height of 70 1/2" for forward reach		205.1	Extend the controls to a height of 48", per 4.2.5.	N/A		
			Semi Private			308.2.1				
182	1988	2	Rooms 227 & 232	Push side of door only has 2" clear floor space on		404.1	Reverse the latch and hinge side so door swings from the opposite	N/A		
	. 300		Semi Private	latch side.	t -		side of frame.			
			Commit invato	into in one of	1	101.2.1	oldo or marrior			
					1	 				
					1					
183	1988	2	Rooms 227 & 232	Coat hook is 70 1/2" AFF.		308 2 4	Lower or provide additional hook, per 4.2.5 or 4.2.6.	N/A		
103	1300		Semi Private	Out 1100K 13 / U 1/2 / Al 1 .	1	308.3.1		IN/A		
			Ocini Filvate		1	300.3.1		1		
					1	1		1		
					\vdash					
							Install a 42 grap par aside the water closet at a neight of 33 -35 to			
					1		the center of the bar. If a 42" grab bar will not fit within the dimensions	1]	
								l		
					1		of the existing space, then install the longest standard length bar that	1]	
							will fit within the existing space, such that it does not protrude greater	l		
184	1988	2	Rooms 227 & 232	Grab bar on the side of the toilet is 24" in length and			than 54 inches from wall behind water closet.	N/A		
			Semi Private	there is not a grab bar behind the toilet.		604.5.2				
			•		•		•			

					1		Reconfigure valve to wide side (including, if applicable, replacement of			
							flush tank), or install automatic flush device as an equivalent			
185	1988	2	Rooms 227 & 232	Flush valve at a height of 51"		604.6	facilitation.	N/A		
			Semi Private							
					1					
					+-					
					+		Relocate the mirror to 40" in height to the reflective edge, per 4.19.6,			
400	4000	_	D 007 0 000	NEW YORK AND		000.0		A1/A		
186	1988	2	Rooms 227 & 232	Mirror at 41 1/2"AFF to bottom of reflective edge.	1	603.3	or install full-length mirror.	N/A		
			Semi Private							
							Provide a shower seat per § 4.21.3, or make a portable seat available			
							and train medical personnel to provide assistance when necessary or			
							required, or provide a wheelchair accessible shower and shower			
407	4000	_	D 007 0 000	Maria di Santa da Carata d		000.4		N1/A		
187	1988	2	Rooms 227 & 232	No wall mounted seat in shower area.	1	608.4	wheelchair.	N/A		
			Semi Private		1	610.1				
							Reconfigure valve to wide side (including, if applicable, replacement of			
							flush tank), or install automatic flush device as an equivalent			
188	1988	2	Room 232	Flush valve not on wide side.		6046	facilitation.	107		
100	1900			Flush valve not on wide side.	4	004.0	racilitation.	107		
			Semi Private							
189	1988	2	Speech Therapy Rooms	Sign does not have braille.		703.3	Provide braille signage, per 4.30.	N/A		
			1,				0 0 71			
					1					
					4					
	v									
Item	Year		Area of						Estimated	
#	Built	Floor	Condition	Condition	TC	ADAAG	Recommendation	Photo	Estimated Cost	Comments
		Floor 2	Condition Water Cooler by West	Condition Insufficient knee clearance of 25".	тс	ADAAG 606.2	Recommendation Reconfigure fountain to provide 27" knee clearance, per 4.15.5.	Photo N/A		Comments
#	Built	Floor 2	Condition		TC	ADAAG 606.2	Recommendation Reconfigure fountain to provide 27" knee clearance, per 4.15.5.			Comments
#	Built	Floor 2	Condition Water Cooler by West		TC	ADAAG 606.2	Recommendation Reconfigure fountain to provide 27* knee clearance, per 4.15.5.			Comments
#	Built	Floor 2	Condition Water Cooler by West		TC	ADAAG 606.2	Recommendation Reconfigure fountain to provide 27" knee clearance, per 4.15.5.			Comments
#	Built	Floor 2	Condition Water Cooler by West		TC	ADAAG 606.2	Recommendation Reconfigure fountain to provide 27" knee clearance, per 4.15.5.			Comments
190	Built 1988	2	Condition Water Cooler by West Restrooms	Insufficient knee clearance of 25".	TC	606.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5.	N/A		Comments
#	Built	Floor 2	Condition Water Cooler by West		TC	703.4.1	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30.			Comments
190	Built 1988	2	Condition Water Cooler by West Restrooms	Insufficient knee clearance of 25".	TC	606.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30.	N/A		Comments
190	Built 1988	2	Condition Water Cooler by West Restrooms	Insufficient knee clearance of 25".	TC	703.4.1	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30.	N/A		Comments
190	Built 1988	2	Condition Water Cooler by West Restrooms	Insufficient knee clearance of 25".	TC	703.4.1	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30.	N/A		Comments
190	1988 1988	2	Condition Water Cooler by West Restrooms West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening.	TC	703.4.1 703.4.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30.	N/A 108		Comments
190	Built 1988	2	Condition Water Cooler by West Restrooms	Insufficient knee clearance of 25".	TC	703.4.1 703.4.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30.	N/A		Comments
190	1988 1988	2	Condition Water Cooler by West Restrooms West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening.	TC	703.4.1 703.4.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30.	N/A 108		Comments
190	1988 1988	2	Condition Water Cooler by West Restrooms West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening.	TC	703.4.1 703.4.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30.	N/A 108		Comments
190	1988 1988	2	Condition Water Cooler by West Restrooms West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening.	TC	703.4.1 703.4.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30.	N/A 108		Comments
190	1988 1988	2	Condition Water Cooler by West Restrooms West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening.	TC	703.4.1 703.4.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30.	N/A 108		Comments
190	1988 1988	2	Condition Water Cooler by West Restrooms West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening.	TC	703.4.1 703.4.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30.	N/A 108		Comments
190	1988 1988	2	Condition Water Cooler by West Restrooms West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening.	TC	703.4.1 703.4.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30. Provide braille signage, per 4.30.	N/A 108		Comments
190	1988 1988	2	Condition Water Cooler by West Restrooms West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening.	TC	703.4.1 703.4.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30. Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed	N/A 108		Comments
190	1988 1988	2	Condition Water Cooler by West Restrooms West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening.	TC	703.4.1 703.4.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30. Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an	N/A 108		Comments
# 190 191 192	1988 1988	2 2 2	Condition Water Cooler by West Restrooms West Men's Restroom West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening. Sign does not have braille.	TC	703.4.1 703.4.2 703.3	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30. Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light	108 108		Comments
190	1988 1988	2 2 2	Condition Water Cooler by West Restrooms West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening.	TC	703.4.1 703.4.2 703.3	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30. Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an	N/A 108		Comments
# 190 191 192	1988 1988	2 2 2	Condition Water Cooler by West Restrooms West Men's Restroom West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening. Sign does not have braille.	TC	703.4.1 703.4.2 703.3	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30. Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light	108 108		Comments
# 190 191 192	1988 1988	2 2 2	Condition Water Cooler by West Restrooms West Men's Restroom West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening. Sign does not have braille.	TC	703.4.1 703.4.2 703.3	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30. Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light	108 108		Comments
# 190 191 192	1988 1988	2 2 2	Condition Water Cooler by West Restrooms West Men's Restroom West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening. Sign does not have braille.	TC	703.4.1 703.4.2 703.3	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30. Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light	108 108		Comments
# 190 191 192	1988 1988	2 2 2	Condition Water Cooler by West Restrooms West Men's Restroom West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening. Sign does not have braille.	TC	703.4.1 703.4.2 703.3	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30. Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light	108 108		Comments
191	1988 1988 1988	2 2 2	Condition Water Cooler by West Restrooms West Men's Restroom West Men's Restroom West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening. Sign does not have braille. Door pressure is 11lbf.	TC	703.4.1 703.4.2 703.3 404.2.9	Relocate signage to latch side of door, per 4.30. Provide braille signage, per 4.30. Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door.	108 108		Comments
# 190 191 192	1988 1988	2 2 2	Condition Water Cooler by West Restrooms West Men's Restroom West Men's Restroom	Insufficient knee clearance of 25". Signs are located on door, not latch side of opening. Sign does not have braille.	TC	703.4.1 703.4.2 703.3 404.2.9	Reconfigure fountain to provide 27" knee clearance, per 4.15.5. Relocate signage to latch side of door, per 4.30. Provide braille signage, per 4.30. Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light	108 108		Comments

	1			Г	_	Contomotically. Can note above item #142 of this re	1	
—						automatically. See note above item #143 of this report.	}	
						Install a 42 grab par aside the water closet at a neight of 33 -36 to		
						the center of the bar. If a 42" grab bar will not fit within the dimensions		
						of the existing space, then install the longest standard length bar that		
		_				will fit within the existing space, such that it does not protrude greater		
195	1988	2	West Men's Restroom	Grab bar on the side of the toilet is 36" in length.	604.5	1 than 54 inches from wall behind water closet.	109	
					609.4			
						Install a 36" grab bar behind the water closet at a height of 33"-36" to		
						the center of the bar. If a 36" grab bar will not fit within the dimensions		
						of the space, then install the longest standard length bar that will fit		
196	1988	2	West Men's Restroom	Grab bar behind the toilet is only 24" in length.		within the existing space, not less than 24 inches in length.	109	
					609.4			
						Relocate the mirror to 40" in height to the reflective edge, per 4.19.6,		
197	1988	2	West Men's Restroom	Mirror at 48 1/2"AFF to bottom of reflective edge.	603.3	or install full-length mirror.	110	
198	1988	2	West Men's Restroom	The forward approach soap dispenser is 50" high.	308.2	Lower the soap dispenser to a maximum height of 48" for a forward	110	
						approach.		
						Replace the water closet with one that is between 17"-19" in height to		Ų
199	1988	2	West Men's Restroom	Toilet is 15 1/2" to seat top.	604.4	the top of the toilet seat, or install a riser as an equivalent facilitation.	109	
						Reconfigure valve to wide side (including, if applicable, replacement of		
						flush tank), or install automatic flush device as an equivalent		
200	1988	2	West Men's Restroom	Flush control is not on wide side.	604.0	facilitation.	109	
					_			

				•						
1							Install ADA compliant strobes if and when replacing or rebuilding			
							existing fire alarm system. Strobes should be installed in general			
							public areas, including cafeterias, vending areas, retail pharmacies,			
							gift shops, chapels, public restrooms, lobbies, waiting rooms,			
							walkways and corridors, business office areas where the public is			
							normally invited (e.g., cashier or personnel office for receipt of			
							applications), conference rooms and classrooms open to the public,			
							and enclosed dressing rooms. Strobes should not be installed in			
							patient rooms (including restrooms in patient rooms), operating			
							rooms, surgical suites and preparation areas, recovery rooms, areas			
							where the patient is undergoing or recovering from anesthesia,			
							emergency department examination and treatment rooms, ICU rooms			
							and other special areas for admitted patients such as NICU or PACU,			
							blood draw and laboratory areas, imaging rooms and diagnostic			
							testing or procedure rooms, psychiatric wards generally, physical			
							therapy training and rehabilitation areas to the extent supervised by			
							medical personnel (except not if exercise areas or equipment are			
							available for use by the general public), and other areas where			
201	1988	2	West Men's Restroom	No visual strobe in area.	1	215.1	admitted patients are under the supervision of facility personnel.	N/A		l
							, , , , , , , , , , , , , , , , , , , ,			
-	1	1			+-	 		l —		-
	ļ	1			1-					
Item	Year		Area of						Estimated	
#		Floor		Condition	TC	ADAAG	Recommendation	Photo	Cost	Comments
202	1988		West Women's	Signs are located on door, not latch side of opening.	10		Relocate signage to latch side of door, per 4.30.	111	COSL	Comments
202	1900			Signs are located on door, not laten side or opening.	 		Relocate signage to laten side of door, per 4.30.	111		
			Restroom			703.4.2				
202	1000	2	West Wemen's	Sign doos not have braille		702.2	Provide braille signage, per 4.20	111		
203	1988	2	West Women's	Sign does not have braille.		703.3	Provide braille signage, per 4.30.	111		
203	1988	2	West Women's Restroom	Sign does not have braille.		703.3	Provide braille signage, per 4.30.	111		
203	1988	2		Sign does not have braille.		703.3	Provide braille signage, per 4.30.	111		
203	1988	2		Sign does not have braille.		703.3	Provide braille signage, per 4.30.	111		
203	1988	2		Sign does not have braille.		703.3	Provide braille signage, per 4.30.	111		
203	1988	2		Sign does not have braille.		703.3	Provide braille signage, per 4.30.	111		
203	1988	2		Sign does not have braille.		703.3		111		
203	1988	2		Sign does not have braille.		703.3	Adjust closer to an opening force of 5lbf or less, and a closing speed	111		
203	1988	2		Sign does not have braille.		703.3	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an	111		
203	1988	2		Sign does not have braille.		703.3	Adjust closer to an opening force of 5lbf or less, and a closing speed	111		
			Restroom				Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light			
203	1988		Restroom West Women's	Sign does not have braille. Door pressure is 12lbf.			Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light	111		
			Restroom				Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light			
			Restroom West Women's				Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light			
			Restroom West Women's				Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light			
			Restroom West Women's				Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light			
204	1988	2	West Women's Restroom	Door pressure is 12lbf.		404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door.	111		
		2	West Women's Restroom West Women's	Door pressure is 12lbf. Door swings into restroom, obstructing the clear floor		404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space.	111		
204	1988	2	West Women's Restroom	Door pressure is 12lbf.		404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches	111		
204	1988	2	West Women's Restroom West Women's	Door pressure is 12lbf. Door swings into restroom, obstructing the clear floor		404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space.	111		
204	1988	2	West Women's Restroom West Women's	Door pressure is 12lbf. Door swings into restroom, obstructing the clear floor		404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches	111		
204	1988	2	West Women's Restroom West Women's	Door pressure is 12lbf. Door swings into restroom, obstructing the clear floor		404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches automatically. See note above item #143 of this report.	111		
204	1988	2	West Women's Restroom West Women's	Door pressure is 12lbf. Door swings into restroom, obstructing the clear floor		404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches	111		
204	1988	2	West Women's Restroom West Women's	Door pressure is 12lbf. Door swings into restroom, obstructing the clear floor		404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches automatically. See note above item #143 of this report.	111		
204	1988	2	West Women's Restroom West Women's	Door pressure is 12lbf. Door swings into restroom, obstructing the clear floor		404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches automatically. See note above item #143 of this report. Install a 42 grap bar aside the water closet at a neight of 33-36 to the center of the bar. If a 42" grab bar will not fit within the dimensions	111		
204	1988	2	West Women's Restroom West Women's	Door pressure is 12lbf. Door swings into restroom, obstructing the clear floor		404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches automatically. See note above item #143 of this report. Install a 42 grap par aside the water closer at a neight of 33-35 to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that	111		
204	1988	2	West Women's Restroom West Women's	Door pressure is 12lbf. Door swings into restroom, obstructing the clear floor		404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches automatically. See note above item #143 of this report. Install a 42 grap bar aside the water closet at a neight of 33-36 to the center of the bar. If a 42" grab bar will not fit within the dimensions	111		
204	1988	2	West Women's Restroom West Women's Restroom	Door pressure is 12lbf. Door swings into restroom, obstructing the clear floor space.		404.2.9 604.8. 1.2	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches automatically. See note above item #143 of this report. Install a 42 grap bar aside the water closet at a neight or 33 -36 to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater	111		
204	1988	2	West Women's Restroom West Women's Restroom West Women's West Women's	Door pressure is 12lbf. Door swings into restroom, obstructing the clear floor		404.2.9 604.8. 1.2	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches automatically. See note above item #143 of this report. Install a 42 grap par aside the water closer at a neight of 33-35 to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that	111		
204	1988	2	West Women's Restroom West Women's Restroom	Door pressure is 12lbf. Door swings into restroom, obstructing the clear floor space.		404.2.9 604.8. 1.2	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches automatically. See note above item #143 of this report. Install a 42 grap bar aside the water closet at a neight or 33 -36 to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater	111		
204	1988	2	West Women's Restroom West Women's Restroom West Women's West Women's	Door pressure is 12lbf. Door swings into restroom, obstructing the clear floor space.		404.2.9 604.8. 1.2	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches automatically. See note above item #143 of this report. Install a 42 grap bar aside the water closet at a neight or 33 -36 to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater	111		
204	1988	2	West Women's Restroom West Women's Restroom West Women's West Women's	Door pressure is 12lbf. Door swings into restroom, obstructing the clear floor space.		404.2.9 604.8. 1.2	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches automatically. See note above item #143 of this report. Install a 42 grap bar aside the water closet at a neight or 33 -36 to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater	111		
204	1988	2	West Women's Restroom West Women's Restroom West Women's West Women's	Door pressure is 12lbf. Door swings into restroom, obstructing the clear floor space.		404.2.9 604.8. 1.2	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door. Install a right out-swing door to swing out of restroom floor space. Door will also require a power opener if the door handle latches automatically. See note above item #143 of this report. Install a 42 grap bar aside the water closet at a neight or 33 -36 to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater	111		

207	1988	2	West Women's Restroom	Grab bar behind the toilet is only 24" in length.		604.5.2 609.4	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	112	
							Relocate the mirror to 40" in height to the reflective edge, per 4.19.6,		
208	1988	2	West Women's	Mirror at 48 1/2"AFF to bottom of reflective edge.		603.3	or install full-length mirror.	113	
200	1000		Restroom	William at 40 1/2 / it is bottom of remotive dage.		000.0	or motern territoring at training at	110	
209	1988	2	West Women's	The forward approach soap dispenser is 50" high.		308.2.1	Lower the soap dispenser to a maximum height of 48" for a forward	113	
-			Restroom				approach.		
-									
				_ ,, , , , , , , , , , , , , , , , , ,			Replace the water closet with one that is between 17"-19" in height to		
210	1988	2	West Women's	Toilet is 15 1/2" to seat top.		604.4	the top of the toilet seat, or install a riser as an equivalent facilitation.	112	
			Restroom						
1					1 1			l	1 1