

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

This facility has 3 separate lots. The staff lot to the left has 38 standard spaces. Main hospital parking has 29 standard, 9 physician, and 1 designated accessible space. The Outpatient lot has 27 standard, and 5 designated accessible spaces.

Item #	Floor	Yr. Built	Area Of	Condition	ADAAG	Recommendation	Photo
001	1	1983	Main Entry	No accessible route from public walkway to main entry.	206.2.1	Provide an accessible route in area shown in photo 006. This area has a slope of 1:24.	004 005
002	1	1983	Outpatient Parking	Access aisles are not on shortest accessible route to main entry.	208.3.1	Relocate the spaces or provide an accessible route.	007
003	1	1983	Outpatient Parking	The designated accessible space has a cross slope of 1:32.	502.4	Grade area to 1:50, or relocate spaces to a level area that is on an accessible route to the entry.	007
004	1	1983	Outpatient Parking	The designated accessible spaces do not have signage.	502.6	Provide signage at all accessible spaces, per 4.6.4.	007 008
005	1	1983	Outpatient Parking	There is not a space marked van accessible, per 4.1.2 (5)(b)	208.2.4	Mark at least one space van accessible, per 4.1.2 (5)(b).	007 008
006	1	1983	Main Parking	The designated accessible space has a long slope of 1:20.	502.4	Grade area to 1:50, or relocate spaces to a level area that is on an accessible route to the entry.	009
007	1	1983	Main Parking	The designated accessible spaces do not have signage.	502.6	Provide signage at all accessible spaces, per 4.6.4.	009
008	1	1983	Main Parking	There is not a space sized or marked van accessible, per 4.1.2 (5)(b)	208.2.4	Make at least one space van accessible, per 4.1.2 (5)(b).	009
009	1	1983	Men's Lobby Restroom	Door pressure is 15lbf.	404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door.	N/A

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
010	1	1983	Women's Lobby Restroom	Door pressure is 15lbf.	404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door.	N/A
011	1	1983	Speech, Language, Psych. Area	Door handle is knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	010
012	1	1983	Speech, Language, Psych. Area	Sign does not have braille.	703.3	Provide braille signage, per 4.30.	010
013	1	1983	Lobby	Fire extinguisher protrudes 8" from wall.	204.1	As permitted by local fire codes, remove, relocate off accessible route and or path of circulation, create cane detectable condition at or below 27" AFF, or replace with flush mounted housing.	011
014	1	1983	East Wing Hall	Fire extinguisher protrudes 8" from wall.	204.1	As permitted by local fire codes, remove, relocate off accessible route and or path of circulation, create cane detectable condition at or below 27" AFF, or replace with flush mounted housing.	011
015	1	1983	West Wing Hall	Fire extinguisher protrudes 8"	204.1	As permitted by local fire codes, remove, relocate off accessible route and or path of circulation, create cane detectable condition at or below 27" AFF, or replace with flush mounted housing.	011

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
				from wall.			
016	1	1983	Admissions, from Lobby	Door handle is knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	012
017	1	1983	Admissions, from Lobby	Pull side of door has 9" clear floor space.	404.2.4	Move desk to provide sufficient clear floor space, per 4.13.6.	013
018	1	1983	Admissions, from Lobby	Insufficient clear floor space on pull side of door.	404.2.4	Move furniture to provide sufficient clear floor space, per 4.13.6.	013
019	1	1983	"Information" sign in Hallway	Sign protrudes 12" from wall.	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	014
020	1	1983	Intervention Pain Hallway	Fire extinguisher protrudes 8" from wall.	204.1	As permitted by local fire codes, remove, relocate off accessible route and or path of circulation, create cane detectable condition at or below 27" AFF, or replace with flush mounted housing.	011
021	1	1983	Radiology Restroom	Mirror at 42 1/2".	603.3	Relocate the mirror to 40" in height to the reflective edge, per 4.19.6, or install full-length mirror.	015
022	1	1983	Radiology Restroom	Seat cover dispenser is 65" high.	205.1	Lower the cover dispenser to a maximum height of 48" for a forward approach.	015
023	1	1983	Radiology Restroom	Seat cover dispenser is not on an accessible route.	205.1	Relocate dispenser to an area on an accessible route.	015

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
024	1	1983	Radiology Restroom	Lavatory hot water and drain pipes are exposed.	606.5	Provide pipe insulation on hot water pipe and drain pipe.	015
025	1	1983	Dining Room	Top controls on sandwich machine cannot be reached on a forward approach.	205.1	Relocate machine 8" to left to provide side reach capability, per 4.2.6.	016
026	1	1983	Dining Room	Fire extinguisher protrudes 8" from wall.	204.1	As permitted by local fire codes, remove, relocate off accessible route and or path of circulation, create cane detectable condition at or below 27" AFF, or replace with flush mounted housing.	017
027	1	1983	Outpatient Wing	Door handle is knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	N/A
028	1	1983	Outpatient Wing	Sign does not have braille.	703.3	Provide braille signage, per 4.30.	018

Facility #: 03-0048-00  
 Facility Type: IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp. Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
029	1	1983	Day Rehab./ Group Room	No visual strobe in area.	215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
						Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	
030	1	1983	Outpatient Lobby	No visual strobe in area.	215.1		N/A
031	1	1983	Outpatient Restroom	Sign does not have braille.	703.3	Provide braille signage, per 4.30.	019
032	1	1983	Outpatient Restroom	Improper sign location.	703.4	Provide signage, per 4.30.	019

Facility #: 03-0048-00  
 Facility Type: IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
033	1	1983	Outpatient Restroom	Cabinet protrudes 9 1/2" from wall at a height of 47 1/2".	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	020
034	1	1983	Outpatient Restroom	Lavatory pipes protude 7" from wall at a height of 6".	606.2	Reconfigure plumbing per 4.19.2, figure 31.	020
035	1	1983	Outpatient Restroom	Lavatory too high at 34 1/2" to the rim.	606.3	Relocate the lavatory to 34" in height to the rim, per 4.19.2.	020
036	1	1983	Outpatient Restroom	Mirror at 41 1/2".	603.3	Relocate the mirror to 40" in height to the reflective edge, per 4.19.6, or install full-length mirror.	020
037	1	1983	Outpatient Restroom	Toilet bowl is 19" from side wall.	604.2	Modify to make compliant, whether by moving toilet, moving partition and/or wall so that toilet bowl is 16-19 inches from wall.	020
038	1	1983	Outpatient Restroom	Grab bars on the side and rear of the toliet at a height of 32 1/4"- 32 1/2".	604.5	Relocate the grab bar to 33"-36" in height to the center of the bar, per 4.26.	020
039	1	1983	Women's Locker room	Sign does not have braille.	703.3	Provide braille signage, per 4.30.	N/A
040	1	1983	Women's Locker room	Door pressure is 7lbf.	404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door.	N/A

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
041	1	1983	Women's Locker room	Coat hook is 62" high.	225.2	Lower or provide additional hook, per 4.2.5 or 4.2.6.	N/A
042	1	1983	Women's Locker room	Mirror at 41 1/2".	603.3	Relocate the mirror to 40" in height to the reflective edge, per 4.19.6, or install full-length mirror.	021
043	1	1983	Spinal Dressing Female Side	Door handle is knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	N/A
044	1	1983	Men's Locker room	Sign does not have braille.	703.3	Provide braille signage, per 4.30.	N/A
045	1	1983	Men's Locker room	Door pressure is 12lbf.	404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door.	N/A
046	1	1983	Men's Locker room	Mirror at 42".	603.3	Relocate the mirror to 40" in height to the reflective edge, per 4.19.6, or install full-length mirror.	021
047	1	1983	Men's Locker room	Lavatory too high at 34 1/2" to the rim.	606.3	Relocate the lavatory to 34" in height to the rim, per 4.19.2.	021
048	1	1983	Men's Locker room	Edge of the urinal is at a height of 19"	605.2	Relocate the urinal to a height of 17", per 4.18.2	021
049	1	1983	Men's Locker room	Urinal flush valve not on wide side.	N/A	Reconfigure valve to wide side.	021

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
050	1	1983	Spinal Dressing Men's Side	Door handle is knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	N/A
051	1	1983	Pool Area	There is no detectable warning along pool edge.	N/A	Provide detectable warning, per 4.29.6.	023
052	1	1983	Pool Area	No grab bars in shower area.	608.3	Install grab bars per ADAAG 4.16.4. If the dimensions of the space prohibit a 36" and/or 42" grab bar, then install the longest standard bars possible in the space.	024
053	1	1983	Outpatient Exercise Room	No signage identifying room.	703.3	Provide signage, per 4.1.2(7).	025

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
054	1	1983	Treatment Rooms 1,2,3, 6-10	No visual strobe in area.	215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A
055	1	1983	Material Safety Data	MSDS rack protrudes 5" from	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	N/A

Facility #: 03-0048-00  
Facility Type:IRH  
Square Footage: 84,528

1850 Normandie Dr.  
York, Pa. 17404

AAF #: 264  
Insp.Date: 10/24/03  
Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
			Sheets (MSDS) Rack	wall at a height of 42".			
056	1	1983	Hallway	Phone protrudes 6 1/2" from wall	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	N/A
057	1	1983	Gym Restroom	Sign does not have braille.	703.3	Provide braille signage, per 4.30.	026

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
						Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	
058	1	1983	Gym Restroom	No visual strobe in area.	215.1		N/A
059	1	1983	Gym Restroom	Mirror at 42".	603.3	Relocate the mirror to 40" in height to the reflective edge, per 4.19.6, or install full-length mirror.	027

Facility #: 03-0048-00  
Facility Type:IRH  
Square Footage: 84,528

1850 Normandie Dr.  
York, Pa. 17404

AAF #: 264  
Insp.Date: 10/24/03  
Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
060	1	1983	Gym Restroom	Cabinet protrudes 7 1/4" from wall at a height of 52 1/2".	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	028
061	1	1983	West Wing Water fountain	Insufficient knee clearance of 28 1/2".	602.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5.	029

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
						Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	
062	1	1983	Day Room	No visual strobe in area.	215.1		N/A
063	1	1983	Day Room	Television is unable to provide closed captioning.	28 CFR 36.3 c	Replace existing TV with a closed caption compatible TV.	030

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
064	1	1983	Hallway Outside Rm's. 301-304 Common Use Shower	Fire extinguisher protrudes 8" from wall.	204.1	As permitted by local fire codes, remove, relocate off accessible route and or path of circulation, create cane detectable condition at or below 27" AFF, or replace with flush mounted housing.	011
065	1	1983	301-304 Common Use Shower	No grab bars in shower area.	608.3	Install grab bars per ADAAG 4.16.4. If the dimensions of the space prohibit a 36" and/or 42" grab bar, then install the longest standard bars possible in the space.	031
066	1	1983	301-304 Common Use Shower	No seat in shower area.	608.4	Provide a shower seat per § 4.21.3, or make a portable seat available and train medical personnel to provide assistance when necessary or required, or provide a wheelchair accessible shower and shower wheelchair.	031
067	1	1983	326-329 Common Use Shower	Urinal flush valve not on wide side.	N/A	Reconfigure valve to wide side.	032
068	1	1983	326-329 Common Use Shower	Mirror at 40 1/2".	603.3	Relocate the mirror to 40" in height to the reflective edge, per 4.19.6, or install full-length mirror.	032
069	1	1983	326-329 Common Use Shower	Lavatory hot water and drain pipes are exposed.	606.5	Provide pipe insulation on hot water pipe and drain pipe.	032

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
070	1	1983	326-329 Common Use Shower	Grab bar behind the toilet is 24" in length.	604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	032
071	1	1983	326-329 Common Use Shower	No seat in shower area.	608.4	Provide a shower seat per § 4.21.3, or make a portable seat available and train medical personnel to provide assistance when necessary or required, or provide a wheelchair accessible shower and shower wheelchair.	033
072	1	1983	Hallway Outside Rm's. 326-329 Common Use Shower	Fire extinguisher protrudes 8" from wall.	204.1	As permitted by local fire codes, remove, relocate off accessible route and or path of circulation, create cane detectable condition at or below 27" AFF, or replace with flush mounted housing.	011
073	1	1983	Room 327 semi-private	Sharps box protrudes 5" from wall.	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	N/A

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
074	1	1983	Room 327 semi-private	Cabinet protrudes 8" from wall at a height of 36".	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	034
075	1	1983	Room 327 semi-private	No visual strobe in area.	215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
076	1	1983	Room 327 semi-private	Closet hanger at a height of 64" for forward reach	225.2	Lower the hanger to a height of 48", per 4.2.5.	035
077	1	1983	Room 327 semi-private	Urinal flush valve not on wide side.	N/A	Reconfigure valve to wide side.	036
078	1	1983	Room 327 semi-private	Grab bar behind the toilet is at a height of 32 1/2" to the top.	604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	036
079	1	1983	Room 327 semi-private	Grab bar on the side of the toilet is at a height of 32 1/2" to top.	604.5.1	Install a 42" grab bar aside the water closet at a height of 33"-36" to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater than 54 inches from wall behind water closet.	036
080	1	1983	Room 327 semi-private	Coat hook is 71" high.	225.2	Lower or provide additional hook, per 4.2.5 or 4.2.6.	N/A

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
						Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	
081	1	1983	Incentives Area-Lobby	No visual strobe in area.	215.1		N/A
082	1	1983	Rooms 305-314 Hallway	Fire extinguisher protrudes 8" from wall.	204.1	As permitted by local fire codes, remove, relocate	011

Facility #: 03-0048-00  
Facility Type:IRH  
Square Footage: 84,528

1850 Normandie Dr.  
York, Pa. 17404

AAF #: 264  
Insp.Date: 10/24/03  
Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
083	1	1983	Room 306 semi-private	Sharps box protrudes 5" from wall.	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	N/A
084	1	1983	Room 306 semi-private	Cabinet protrudes 8" from wall at a height of 36".	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	034

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
						Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	
085	1	1983	Room 306 semi-private	No visual strobe in area.	215.1		N/A
086	1	1983	Room 306 semi-private	Closet hanger at a height of 64" for forward reach	225.2	Lower the hanger to a height of 48", per 4.2.5.	035
087	1	1983	Room 306 semi-private	Urinal flush valve not on wide side.	N/A	Reconfigure valve to wide side.	037

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
088	1	1983	Room 306 semi-private	No grab bar behind the toilet.	604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	037
089	1	1983	Room 306 semi-private	Grab bar on the side of the toilet is at a height of 32 1/2" to top.	604.5.1	Install a 42" grab bar aside the water closet at a height of 33"-36" to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater than 54 inches from wall behind water closet.	037
090	1	1983	Room 306 semi-private	Coat hook is 71" high.	225.2	Lower or provide additional hook, per 4.2.5 or 4.2.6.	N/A
091	1	1983	Rooms 315-325 Hallway	Fire extinguisher protrudes 8" from wall.	204.1	As permitted by local fire codes, remove, relocate off accessible route and or path of circulation, create cane detectable condition at or below 27" AFF, or replace with flush mounted housing.	011
092	1	1983	Room 316- Private	Sharps box protrudes 5" from wall.	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	N/A

Facility #: 03-0048-00  
 Facility Type: IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp. Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
093	1	1983	Room 316- Private	Cabinet protrudes 8" from wall at a height of 36".	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	034
094	1	1983	Room 316- Private	No visual strobe in area.	215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
095	1	1983	Room 316- Private	Closet hanger at a height of 64" for forward reach	225.2	Lower the hanger to a height of 48", per 4.2.5.	035
096	1	1983	Room 316- Private	Urinal flush valve not on wide side.	N/A	Reconfigure valve to wide side.	037
097	1	1983	Room 316- Private	No grab bar behind the toilet.	604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	037
098	1	1983	Room 316- Private	Grab bar on the side of the toilet is at a height of 32 1/2" to top.	604.5.1	Install a 42" grab bar aside the water closet at a height of 33"-36" to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater than 54 inches from wall behind water closet.	037
099	1	1983	Room 316- Private	Coat hook is 71" high.	225.2	Lower or provide additional hook, per 4.2.5 or 4.2.6.	N/A

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
100	1	2002	Room 322	No visual strobe in area.	215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A
101	1	2002	Room 322	Sharps box protrudes 5" from wall.	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	N/A

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
102	1	2002	Room 322	Cabinet protrudes 8" from wall at a height of 37".	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	038
103	1	1983	East Wing Water-fountain	Insufficient knee clearance of 26 1/2".	602.2	Reconfigure fountain to provide 27" knee clearance, per 4.15.5.	029
104	1	1983 2002	All Hallways	Fire extinguisher protrudes 8" from wall.	204.1	As permitted by local fire codes, remove, relocate off accessible route and or path of circulation, create cane detectable condition at or below 27" AFF, or replace with flush mounted housing.	011
105	1	1983	Rooms 225-228 Common Use Showers	Grab bar behind the toilet is 24" in length.	604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	039
106	1	1983	Rooms 225-228 Common Use Showers	Lavatory hot water and drain pipes are exposed.	606.5	Provide pipe insulation on hot water pipe and drain pipe.	039
107	1	1983	Rooms 225-228 Common Use Showers	No seat in shower area.	608.4	Provide a shower seat per § 4.21.3, or make a portable seat available and train medical personnel to provide assistance when necessary or required, or provide a wheelchair accessible shower and shower wheelchair.	040

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
108	1	1983	Rooms 225-228 Common Use Showers	Cabinet protrudes 13 1/2" from wall at a height of 43 1/2".	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	041
109	1	1983	Room 228 Semi Private	Sharps box protrudes 5" from wall.	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	N/A
110	1	1983	Room 228 Semi Private	Cabinet protrudes 8" from wall at a height of 36".	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	040
111	1	1983	Room 228 Semi Private	No visual strobe in area.	215.1	Install ADA compliant strobes if and when replaci	N/A
112	1	1983	Room 228 Semi Private	Closet hanger at a height of 64" for forward reach	225.2	Lower the hanger to a height of 48", per 4.2.5.	035
113	1	1983	Room 228 Semi Private	Flush valve not on wide side.	604.6	Reconfigure valve to wide side (including, if applicable, replacement of flush tank), or install automatic flush device as an equivalent facilitation.	043

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
114	1	1983	Room 228 Semi Private	No grab bar behind the toilet.	604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	043
115	1	1983	Room 228 Semi Private	Grab bar on the side of the toilet is at a height of 32 1/2" to top.	604.5.1	Install a 42" grab bar aside the water closet at a height of 33"-36" to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater than 54 inches from wall behind water closet.	043
116	1	1983	Room 228 Semi Private	Coat hook is 71" high.	225.2	Lower or provide additional hook, per 4.2.5 or 4.2.6.	N/A
117	1	1983	Room 202 Semi Private	Sharps box protrudes 5" from wall.	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	N/A
118	1	1983	Room 202 Semi Private	Cabinet protrudes 8" from wall at a height of 36".	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	038

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
						Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	
119	1	1983	Room 202 Semi Private	No visual strobe in area.	215.1		N/A
120	1	1983	Room 202 Semi Private	Closet hanger at a height of 64" for forward reach	225.2	Lower the hanger to a height of 48", per 4.2.5.	035
121	1	1983	Room 202 Semi Private	Urinal flush valve not on wide side.	N/A	Reconfigure valve to wide side.	044

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
122	1	1983	Room 202 Semi Private	No grab bar behind the toilet.	604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	044
123	1	1983	Room 202 Semi Private	Grab bar on the side of the toilet is at a height of 32 1/2" to top.	604.5.1	Install a 42" grab bar aside the water closet at a height of 33"-36" to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater than 54 inches from wall behind water closet.	044
124	1	1983	Room 202 Semi Private	Coat hook is 71" high.	225.2	Lower or provide additional hook, per 4.2.5 or 4.2.6.	N/A
125	1	1983	Room 316- Private	Sharps box protrudes 5" from wall.	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	N/A
126	1	1983	Room 316- Private	Cabinet protrudes 8" from wall at a height of 36".	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	034

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
						Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	
127	1	1983	Room 316- Private	No visual strobe in area.	215.1		N/A
128	1	1983	Room 316- Private	Closet hanger at a height of 64" for forward reach	225.2	Lower the hanger to a height of 48", per 4.2.5.	035
129	1	1983	Room 316- Private	Urinal flush valve not on wide side.	N/A	Reconfigure valve to wide side.	037

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
130	1	1983	Room 316- Private	No grab bar behind the toilet.	604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	037
131	1	1983	Room 316- Private	Grab bar on the side of the toilet is at a height of 32 1/2" to top.	604.5.1	Install a 42" grab bar aside the water closet at a height of 33"-36" to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater than 54 inches from wall behind water closet.	037
132	1	1983	Room 316- Private	Coat hook is 71" high.	225.2	Lower or provide additional hook, per 4.2.5 or 4.2.6.	N/A
133	1	1983	Room 213 Isolation	Sharps box protrudes 5" from wall.	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	N/A
134	1	1983	Room 213 Isolation	Cabinet protrudes 8" from wall at a height of 36".	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	038

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
						Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	
135	1	1983	Room 213 Isolation	No visual strobe in area.	215.1		N/A
136	1	1983	Room 213 Isolation	Closet hanger at a height of 64" for forward reach	225.2	Lower the hanger to a height of 48", per 4.2.5.	035
137	1	1983	Room 213 Isolation	Urinal flush valve not on wide side.	N/A	Reconfigure valve to wide side.	044

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of	Condition	ADAAG	Recommendation	Photo
138	1	1983	Room 213 Isolation	Grab bar behind the toilet is at a height of 32 1/2" to the top.	604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	044
139	1	1983	Room 213 Isolation	Grab bar on the side of the toilet is at a height of 32 1/2" to top.	604.5.1	Install a 42" grab bar aside the water closet at a height of 33"-36" to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater than 54 inches from wall behind water closet.	044
140	1	1983	Room 213 Isolation	Coat hook is 71" high.	225.2	Lower or provide additional hook, per 4.2.5 or 4.2.6.	N/A
141	1	1983	Room 216 Private	Sharps box protrudes 5" from wall.	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	N/A
142	1	1983	Room 216 Private	Cabinet protrudes 8" from wall at a height of 36".	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	038

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
						Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	
143	1	1983	Room 216 Private	No visual strobe in area.	215.1		N/A
144	1	1983	Room 216 Private	Closet hanger at a height of 64" for forward reach	225.2	Lower the hanger to a height of 48", per 4.2.5.	035
145	1	1983	Room 216 Private	Urinal flush valve not on wide side.	N/A	Reconfigure valve to wide side.	044

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
146	1	1983	Room 216 Private	Grab bar behind the toilet is at a height of 32 1/2" to the top.	604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	044
147	1	1983	Room 216 Private	Grab bar on the side of the toilet is at a height of 32 1/2" to top.	604.5.1	Install a 42" grab bar aside the water closet at a height of 33"-36" to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater than 54 inches from wall behind water closet.	044
148	1	1983	Room 216 Private	Coat hook is 71" high.	225.2	Lower or provide additional hook, per 4.2.5 or 4.2.6.	N/A
149	1	1983	Room 217 Semi Private	Sharps box protrudes 5" from wall.	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	N/A
150	1	1983	Room 217 Semi Private	Cabinet protrudes 8" from	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	038

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
				wall at a height of 36".			
						Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	
151	1	1983	Room 217 Semi Private	No visual strobe in area.	215.1		N/A
152	1	1983	Room 217 Semi Private	Closet hanger at a height of 64" for forward reach	225.2	Lower the hanger to a height of 48", per 4.2.5.	035
153	1	1983	Room 217 Semi Private	Urinal flush valve not on wide side.	N/A	Reconfigure valve to wide side.	044

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
154	1	1983	Room 217 Semi Private	Grab bar behind the toilet is at a height of 32 1/2" to the top.	604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	044
155	1	1983	Room 217 Semi Private	Grab bar on the side of the toilet is at a height of 32 1/2" to top.	604.5.1	Install a 42" grab bar aside the water closet at a height of 33"-36" to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater than 54 inches from wall behind water closet.	044
156	1	1983	Room 217 Semi Private	Coat hook is 71" high.	225.2	Lower or provide additional hook, per 4.2.5 or 4.2.6.	N/A
157	1	1998 2000	Room 220	Sharps box protrudes 5" from wall.	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	N/A
158	1	1998 2000	Room 220	Lavatory too high at 34 1/2" to the rim.	606.3	Relocate the lavatory to 34" in height to the rim, per 4.19.2.	045
159	1	1998	Room 220	Mirror at 41".	603.3	Relocate the mirror to 40" in height to the reflective edge, per 4.19.6, or install full-length mirror.	045

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
		2000					
160	1	1998 2000	Room 220	Improper sign location.	703.4	Provide signage, per 4.30.	045
161	1	1998 2000	Room 220	Toilet bowl is 23 1/2" from side wall.	604.2	Modify to make compliant, whether by moving toilet, moving partition and/or wall so that toilet bowl is 16-19 inches from wall.	044
162	1	1998 2000	Room 220	Cabinet protrudes 8" from wall at a height of 36".	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	038
163	1	1998 2000	Room 220	Coat hook is 71" high.	225.2	Lower or provide additional hook, per 4.2.5 or 4.2.6.	N/A
164	1	1998 2000	Room 219	No grab bar behind the toilet.	604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	044
165	1	1998 2000	Room 219	Sharps box protrudes 5" from wall.	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	N/A

Facility #: 03-0048-00  
 Facility Type: IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp. Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
166	1	1998 2000	Room 219	Cabinet protrudes 8" from wall at a height of 36".	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	038
167	1	1998 2000	Room 219	Coat hook is 71" high.	225.2	Lower or provide additional hook, per 4.2.5 or 4.2.6.	N/A
168	1	1998 2000	Room 219	Improper sign location.	703.4	Provide signage, per 4.30.	N/A
169	1	1983	Speech Therapy	Sign does not have braille.	703.3	Provide braille signage, per 4.30.	N/A
170	1	1983	Speech Therapy	Door handle is knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	N/A

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
171	1	1983	Speech Therapy	No visual strobe in area.	215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A
172	1	1983	Dining	Sharps box protrudes 5" from wall.	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	N/A

Facility #: 03-0048-00  
 Facility Type:IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp.Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
173	1	1983	Dining	No visual strobe in area.	215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A
174	1	1983	Dining	Fire pull box protrudes 5" from	204.1	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectible element with a leading edge at or below 27" AFF.	046

Facility #: 03-0048-00  
 Facility Type: IRH  
 Square Footage: 84,528

1850 Normandie Dr.  
 York, Pa. 17404

AAF #: 264  
 Insp. Date: 10/24/03  
 Confidential

Item #	Floor	Yr. Built	Area Of Condition	Condition	ADAAG	Recommendation	Photo
				wall.			
175	1	1983	Common Shower	Improper sign location.	703.4	Provide signage, per 4.30.	047
176	1	1983	Common Shower	Door handle is knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	047
177	1	1983	Common Shower	No seat in shower area.	608.4	Provide a shower seat per § 4.21.3, or make a portable seat available and train medical personnel to provide assistance when necessary or required, or provide a wheelchair accessible shower and shower wheelchair.	047
178	1	1983	Common Shower	No grab bars in shower area.	608.3	Install grab bars per ADAAG 4.16.4. If the dimensions of the space prohibit a 36" and/or 42" grab bar, then install the longest standard bars possible in the space.	047
179	1	1983	Common Shower	Pull side of door has 14 1/2" clear floor space.	404.2.4	Relocate movable objects from doorway.	047