acilit	y ID#		03-0050-02	1	Δd	dress	2900 Plan Road, Suite 2			
CR #			404		Cit		Altoona			
	state II) #	1677		Sta		PA			
q FT		- <i></i>	4,000			rveyed	9/2/2008			
	у Туре		PT Center			gotiated				
tem	Year		Area of						Estimated	
#		Floor		Condition	тс	ADAAG	Recommendation	Photo		Comme
		king.	Photos 001 & 002.	,			Healthsouth can be accessed through lower level. Suggest providing s	ngnage	directing to lower lev	vei
001	N/A	1	Parking Lot	The riser heights range from 3 1/2" to 6" and are not uniform.		504.2	Modify risers to provide a uniform height.	003		
002	N/A	1	Lobby Restroom	Signs are located on door, not latch side of opening.		703.4.1 703.4.2	Relocate signage to latch side of door, per 4.30.	004		
003	N/A	1	Lobby Restroom	Flush control is not on wide side.		604.6	Reconfigure valve to wide side (including, if applicable, replacement of flush tank), or install automatic flush device as an equivalent facilitation.	005		
004	N/A	1	Lobby Restroom	Grab bar behind the toilet is only 24" in length.		604.5.2 609.4	Install a 36 grap par pening the water closet at a neight of 33 -36 to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	005		
005	N/A	1	Lobby Restroom	Toilet is 15 1/2" to seat top.		604.4	Replace the water closet with one that is between 17"-19" in height to the top of the toilet seat, or install a riser as an equivalent facilitation.	005		