

Facility ID # 03-0076-00  
ACR # 303  
Real Estate ID # 1381  
Sq FT 53,348  
Facility Type IRH

Address 201 Medical Village Drive  
City Edgewood  
State KY  
Date Inspected 03/22/04  
Date Negotiated

<u>Item #</u>	<u>Year Built</u>	<u>Floor</u>	<u>Area of Condition</u>	<u>Condition</u>	<u>ADAAG</u>	<u>Recommendation</u>	<u>Photo</u>
001	1986	1	Main Parking Lot	No accessible route from left space to main entry.	206.1 206.2.2	Provide an accessible route, per § 4.3.2(1)	003
002	1986	1	Main Parking Lot	There is not a space sized or marked van accessible, per § 4.1.2 (5)(b)	502.2 502.6	Make accessible at least 20% of parking spaces provided by HealthSouth for use by patients or visitors of the facility. For every 6 accessible parking spaces, make one a van accessible space.	003
003	1986	1	Side Parking Lot	Access aisles are not on shortest accessible route to main entry.	502.3	Relocate the spaces to the main lot shown in photo 002, and provide signage to this area.	004
004	1986	1	Side Parking Lot	No accessible route from spaces to main entry.	206.1 206.2.2	Relocate the spaces to the main lot shown in photo 002, and provide signage to this area.	004
005	1986	1	Side Parking Lot	There is not a space sized or marked van accessible, per § 4.1.2 (5)(b)	502.2 502.6	Make accessible at least 20% of parking spaces provided by HealthSouth for use by patients or visitors of the facility. For every 6 accessible parking spaces, make one a van accessible space.	004
006	1986	1	Side Parking Lot	The designated accessible space has a long slope of 3%.	502.4	Relocate the spaces to the main lot shown in photo 002, and provide signage to this area.	004
007	1986	1	Route from side lot	Ramp has a run over 30', but no mid landing.	405.7 405.8	Provide handrails on ramp, per § 4.8.5, or provide no access signage and relocate spaces.	005
008	1986	1	Route from side lot	Ramp has a run over 30", but no handrails.	405.7 405.8	Reconfigure ramp to allow a level landing so ramp lengths don't exceed 30', per § 4.8.2, or provide no access signage and relocate spaces.	005
009	1986	1	Lobby	The pay phone does not have volume control.	704.3	Contact vendor to have volume control installed on phone, per § 4.31.5 (2)	N/A

<u>Item #</u>	<u>Year Built</u>	<u>Floor</u>	<u>Area of Condition</u>	<u>Condition</u>	<u>ADAAG</u>	<u>Recommendation</u>	<u>Photo</u>
010	1986	1	All building strobes	Strobes are not proper type.	215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A
011	1986	1	Men's Lobby Restroom	Door pressure is 13lbf.	404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door.	N/A
012	1986	1	Men's Lobby Restroom	Urinal flush valve is at a height of 46"	605.4	Relocate valve to a height of 44", per § 4.18.4.	N/A
013	1986	1	Men's Lobby Restroom	Flush valve not on wide side.	604.6	Reconfigure valve to wide side (including, if applicable, replacement of flush tank), or install automatic flush device as an equivalent facilitation.	006

<u>Item #</u>	<u>Year Built</u>	<u>Floor</u>	<u>Area of Condition</u>	<u>Condition</u>	<u>ADAAG</u>	<u>Recommendation</u>	<u>Photo</u>
014	1986	1	Men's Lobby Restroom	Grab bar on the side of the toilet is 36" in length.	604.5.1 609.4	Install a 42" grab bar aside the water closet at a height of 33"-36" to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater than 54 inches from wall behind water closet.	006
015	1986	1	Men's Lobby Restroom	Mirror at 42 1/2" to reflective edge.	603.3	Relocate the mirror to 40" in height to the reflective edge, per 4.19.6, or install full-length mirror.	007
016	1986	1	Men's Lobby Restroom	Lavatory hot water and drain pipes are exposed.	213.3.4 606.5	Provide pipe insulation on hot water pipe and drain pipe.	007
017	1986	1	Men's Lobby Restroom	No pull handle on partition door.	604.8.1.2	Install pull handle on pull side of door.	N/A

<u>Item #</u>	<u>Year Built</u>	<u>Floor</u>	<u>Area of Condition</u>	<u>Condition</u>	<u>ADAAG</u>	<u>Recommendation</u>	<u>Photo</u>
018	1986	1	Men's Lobby Restroom	No visual strobe in area.	215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A
019	1986	1	Women's Lobby Restroom	Door pressure is 11lbf.	404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door.	N/A
020	1986	1	Women's Lobby Restroom	Pull side of door has 5" clear floor space.	404.2.4	Reconfigure partitions to create 18" on pull side, change door with left out-swing, or provide opener.	008

<u>Item #</u>	<u>Year Built</u>	<u>Floor</u>	<u>Area of Condition</u>	<u>Condition</u>	<u>ADAAG</u>	<u>Recommendation</u>	<u>Photo</u>
021	1986	1	Women's Lobby Restroom	Grab bar on the side of the toilet is 36" in length.	604.5.1 609.4	Install a 42" grab bar, at a height of 33"-36" to the center of the bar, per § 4.26. If a 42" grab bar is not permitted by the dimensions of the space, then keep current grab bar in place, provided that the installation of a 42" grab bar would not be readily achievable (i.e., installation would require expanding the size of the stall, thereby reducing the number of stalls required by local building codes, or if it would require moving a partition wall).	006
022	1986	1	Women's Lobby Restroom	Mirror at 42 1/2" to reflective edge.	603.3	Relocate the mirror to 40" in height to the reflective edge, per 4.19.6, or install full-length mirror.	009
023	1986	1	Women's Lobby Restroom	Lavatory hot water and drain pipes are exposed.	213.3.3.4 606.5	Provide pipe insulation on hot water pipe and drain pipe.	009
024	1986	1	Women's Lobby Restroom	No pull handle on partition door.	604.8.1.2	Install pull handle on pull side of door.	009

<u>Item #</u>	<u>Year Built</u>	<u>Floor</u>	<u>Area of Condition</u>	<u>Condition</u>	<u>ADAAG</u>	<u>Recommendation</u>	<u>Photo</u>
025	1986	1	Women's Lobby Restroom	No visual strobe in area.	215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A
026	1986	1	Admin. Office	Door handle is knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	N/A

<u>Item #</u>	<u>Year Built</u>	<u>Floor</u>	<u>Area of Condition</u>	<u>Condition</u>	<u>ADAAG</u>	<u>Recommendation</u>	<u>Photo</u>
027	1986	1	Admin. Office	No visual strobe in area.	215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A

<u>Item #</u>	<u>Year Built</u>	<u>Floor</u>	<u>Area of Condition</u>	<u>Condition</u>	<u>ADAAG</u>	<u>Recommendation</u>	<u>Photo</u>
028	1986	1	Admin. Waiting	No visual strobe in area.	215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A
029	1986	1	Speech Pathology rooms (3)	Door handle is knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	010

<u>Item #</u>	<u>Year Built</u>	<u>Floor</u>	<u>Area of Condition</u>	<u>Condition</u>	<u>ADAAG</u>	<u>Recommendation</u>	<u>Photo</u>
030	1986	1	Speech Pathology rooms (3)	No visual strobe in area.	215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A
031	1986	1	(1) Speech Room	Insufficient clear floor space on pull side of door.	404.2.4	Remove cabinetry 18" away from door frame.	010
032	1986	1	Neuro Gym	Door handle is knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	N/A
033	1986	1	Neuro Gym Restroom	Door handle is knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	011
034	1986	1	Neuro Gym Restroom	Cabinet protrudes 14" from wall at a height of 57".	204.1 307.2	Remove obstruction, replace with similar item that protrudes less than 4" from the wall, move the item off of the accessible route, raise to above 80" AFF, or install a cane-detectable element with a leading edge at or below 27" AFF.	011

<u>Item #</u>	<u>Year Built</u>	<u>Floor</u>	<u>Area of Condition</u>	<u>Condition</u>	<u>ADAAG</u>	<u>Recommendation</u>	<u>Photo</u>
035	1986	1	Neuro Gym Restroom	Flush valve not on wide side.	604.6	Reconfigure valve to wide side (including, if applicable, replacement of flush tank), or install automatic flush device as an equivalent facilitation.	011
036	1986	1	Neuro Gym Restroom	Grab bars around toilet are not ADA size and type.	604.5.1 604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	011
037	1986	1	Neuro Gym Restroom	Mirror at 43" to reflective edge.	603.3	Relocate the mirror to 40" in height to the reflective edge, per 4.19.6, or install full-length mirror.	011
038	1986	1	Ortho Gym	No visual strobe in area.	215.1	Install ADA compliant strobes if and when replacing or rebuilding existing fire alarm system. Strobes should be installed in general public areas, including cafeterias, vending areas, retail pharmacies, gift shops, chapels, public restrooms, lobbies, waiting rooms, walkways and corridors, business office areas where the public is normally invited (e.g., cashier or personnel office for receipt of applications), conference rooms and classrooms open to the public, and enclosed dressing rooms. Strobes should not be installed in patient rooms (including restrooms in patient rooms), operating rooms, surgical suites and preparation areas, recovery rooms, areas where the patient is undergoing or recovering from anesthesia, emergency department examination and treatment rooms, ICU rooms and other special areas for admitted patients such as NICU or PACU, blood draw and laboratory areas, imaging rooms and diagnostic testing or procedure rooms, psychiatric wards generally, physical therapy training and rehabilitation areas to the extent supervised by medical personnel (except not if exercise areas or equipment are available for use by the general public), and other areas where admitted patients are under the supervision of facility personnel.	N/A

<u>Item #</u>	<u>Year Built</u>	<u>Floor</u>	<u>Area of Condition</u>	<u>Condition</u>	<u>ADAAG</u>	<u>Recommendation</u>	<u>Photo</u>
039	1986	1	Ortho Gym	Door handle is knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	N/A
040	1986	1	Therapy Pool	There is no detectable warning along pool edge.	No req. in 2010 ADA	Provide detectable warning, per § 4.29.6.	012
041	1986	1	Pool Restroom	Door handle is knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	013
042	1986	1	Pool Restroom	No signage identifying room.	216.8	Provide signage, per § 4.1.2(7).	013
043	1986	1	Pool Restroom	Grab bar on the side of the toilet is 36" in length.	604.5.1 609.4	Install a 42" grab bar aside the water closet at a height of 33"-36" to the center of the bar. If a 42" grab bar will not fit within the dimensions of the existing space, then install the longest standard length bar that will fit within the existing space, such that it does not protrude greater than 54 inches from wall behind water closet.	014
044	1986	1	Pool Restroom	Grab bar behind the toilet is 24" in length.	604.5.2 609.4	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	014
045	1986	1	Pool Restroom	Grab bars are at a height of 37".	609.4	Relocate the grab bar to 33"-36" in height to the center of the bar, per § 4.26.	014
046	1986	1	Pool Restroom	Flush valve not on wide side.	604.6	Reconfigure valve to wide side (including, if applicable, replacement of flush tank), or install automatic flush device as an equivalent facilitation.	014
047	1986	1	Pool Restroom	Coat hook is 62" high.	308.2.1 308.3.1	Lower or provide additional hook, per § 4.2.5 or § 4.2.6.	N/A
048	1986	1	Pool Restroom	Mirror at 45" to reflective edge.	603.3	Relocate the mirror to 40" in height to the reflective edge, per 4.19.6, or install full-length mirror.	014
049	1986	1	Pool Restroom	Lavatory hot water and drain pipes are exposed.	213.3.4 606.5	Provide pipe insulation on hot water pipe and drain pipe.	014

<u>Item #</u>	<u>Year Built</u>	<u>Floor</u>	<u>Area of Condition</u>	<u>Condition</u>	<u>ADAAG</u>	<u>Recommendation</u>	<u>Photo</u>
050	1986	1	(2) Showers	Door handle is knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	013
051	1986	1	(2) Showers	No signage identifying room.	216.8	Provide signage, per § 4.1.2(7).	013
052	1986	1	(2) Showers	No seat in shower area.	608.4 610.1	Provide a shower seat per § 4.21.3, or make a portable seat available and train medical personnel to provide assistance when necessary or required, or provide a wheelchair accessible shower and shower wheelchair.	015
053	1986	1	(2) Showers	No shower spray unit.	607.6	Provide shower spray unit, per § 4.21.6.	015
054	1986	1	(2) Showers	Coat hook is 62" high.	308.2.1 308.3.1	Lower or provide additional hook, per § 4.2.5 or § 4.2.6.	N/A
055	1986	1	Psychology, Education, Inpatient Admitting Rooms	Insufficient clear floor space on pull side of doors.	404.2.4	Remove cabinetry 18" away from door frame.	016
056	1986	1	Psychology, Education, Inpatient Admitting Rooms	Door handles are knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	016
057	1986	1	Patient Dining Room	Door handles are knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	017
058	1986	1	Patient Rooms- High Hall Shower	Door pressure is 18lbf.	404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door.	017
059	1986	1	Patient Rooms- High Hall Shower	Door handles are knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	017
060	1986	1	Patient Rooms- High Hall Shower	Lavatory hot water and drain pipes are exposed.	213.3.4 606.5	Provide pipe insulation on hot water pipe and drain pipe.	017

<u>Item #</u>	<u>Year Built</u>	<u>Floor</u>	<u>Area of Condition</u>	<u>Condition</u>	<u>ADAAG</u>	<u>Recommendation</u>	<u>Photo</u>
061	1986	1	Patient Rooms- High Hall Shower	No seat in shower area.	608.4 610.1	Provide a shower seat per § 4.21.3, or make a portable seat available and train medical personnel to provide assistance when necessary or required, or provide a wheelchair accessible shower and shower wheelchair.	N/A
062	1986	1	Patient Rooms- Low Hall Shower	Door pressure is 18lbf.	404.2.9	Adjust closer to an opening force of 5lbf or less, and a closing speed of no less than 3 seconds. If closer is not adjustable, replace with an ADA-compliant closer. If a fire-rated door, adjust closer to be as light as possible while still consistently closing and latching the door.	017
063	1986	1	Patient Rooms- Low Hall Shower	Door handles are knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener..	017
064	1986	1	Patient Rooms- Low Hall Shower	Lavatory hot water and drain pipes are exposed.	213.3.4 606.5	Provide pipe insulation on hot water pipe and drain pipe.	017
065	1986	1	Patient Rooms- Low Hall Shower	No seat in shower area.	608.4 610.1	Provide a shower seat per § 4.21.3, or make a portable seat available and train medical personnel to provide assistance when necessary or required, or provide a wheelchair accessible shower and shower wheelchair.	N/A
066	1986	1	Room 112-private	Blind controls at a height of 62" for forward reach	205.1 308.2.1	Install such that chain control is not higher than 48 inches above finished floor for forward reach and not higher than 54 inches above finished floor for side reach.	N/A
067	1986	1	Room 112-private restroom	Door handles are knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	018
068	1986	1	Room 112-private restroom	No signage identifying room.	216.8	Provide signage, per § 4.1.2(7).	018
069	1986	1	Room 112-private restroom	Mirror at 43" to reflective edge.	603.3	Relocate the mirror to 40" in height to the reflective edge, per 4.19.6, or install full-length mirror.	018
070	1986	1	Room 112-private restroom	Lavatory hot water and drain pipes are exposed.	213.3.4 606.5	Provide pipe insulation on hot water pipe and drain pipe.	018

<u>Item #</u>	<u>Year Built</u>	<u>Floor</u>	<u>Area of Condition</u>	<u>Condition</u>	<u>ADAAG</u>	<u>Recommendation</u>	<u>Photo</u>
071	1986	1	Room 112-private restroom	Grab bars around toilet are not ADA size and type.	604.5.1 604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	018
072	1986	1	Room 117-semi	Blind controls at a height of 62" for forward reach	205.1 308.2.1	Install such that chain control is not higher than 48 inches above finished floor for forward reach and not higher than 54 inches above finished floor for side reach.	N/A
073	1986	1	Room 117-semi restroom	Door handles are knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	018
074	1986	1	Room 117-semi restroom	No signage identifying room.	216.8	Provide signage, per § 4.1.2(7).	018
075	1986	1	Room 117-semi restroom	Mirror at 43" to reflective edge.	603.3	Relocate the mirror to 40" in height to the reflective edge, per 4.19.6, or install full-length mirror.	018
076	1986	1	Room 117-semi restroom	Lavatory hot water and drain pipes are exposed.	213.3.4 606.5	Provide pipe insulation on hot water pipe and drain pipe.	018
077	1986	1	Room 117-semi restroom	Grab bars around toilet are not ADA size and type.	604.5.1 604.5.2	Provide ADA grab bars, per § 4.16.4.	018
078	1986	1	Room 101-private	Blind controls at a height of 62" for forward reach	205.1 308.2.1	Install such that chain control is not higher than 48 inches above finished floor for forward reach and not higher than 54 inches above finished floor for side reach.	N/A
079	1986	1	Room 101-private restroom	Door handles are knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	018
080	1986	1	Room 101-private restroom	No signage identifying room.	216.8	Provide signage, per § 4.1.2(7).	018
081	1986	1	Room 101-private restroom	Mirror at 43" to reflective edge.	603.3	Relocate the mirror to 40" in height to the reflective edge, per 4.19.6, or install full-length mirror.	018

<u>Item #</u>	<u>Year Built</u>	<u>Floor</u>	<u>Area of Condition</u>	<u>Condition</u>	<u>ADAAG</u>	<u>Recommendation</u>	<u>Photo</u>
082	1986	1	Room 101-private restroom	Lavatory hot water and drain pipes are exposed.	213.3.4 606.5	Provide pipe insulation on hot water pipe and drain pipe.	018
083	1986	1	Room 101-private restroom	Grab bars around toilet are not ADA size and type.	604.5.1 604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	018
084	1986	1	Room 107-semi restroom	Blind controls at a height of 62" for forward reach	205.1 308.2.1	Install such that chain control is not higher than 48 inches above finished floor for forward reach and not higher than 54 inches above finished floor for side reach.	N/A
085	1986	1	Room 107-semi restroom	Door handles are knob type and non-compliant.	404.2.7	Remove existing knob and install lever door hardware, or install automatic door opener.	018
086	1986	1	Room 107-semi restroom	No signage identifying room.	216.8	Provide signage, per § 4.1.2(7).	018
087	1986	1	Room 107-semi restroom	Mirror at 43" to reflective edge.	603.3	Relocate the mirror to 40" in height to the reflective edge, per 4.19.6, or install full-length mirror.	018
088	1986	1	Room 107-semi restroom	Lavatory hot water and drain pipes are exposed.	213.3.4 606.5	Provide pipe insulation on hot water pipe and drain pipe.	018
089	1986	1	Room 107-semi restroom	Grab bars around toilet are not ADA size and type.	604.5.1 604.5.2	Install a 36" grab bar behind the water closet at a height of 33"-36" to the center of the bar. If a 36" grab bar will not fit within the dimensions of the space, then install the longest standard length bar that will fit within the existing space, not less than 24 inches in length.	018